

Weld Process Guide

# RAPID X<sup>®</sup> LS

---

Automotive component manufacturers are facing increased demand for better paint adhesion and longer resulting corrosion life of their components. To help meet this challenge, Lincoln Electric has developed a low silicate wire that reduces surface silicates to help improve paint adhesion. The Rapid X<sup>®</sup> process was developed for high travel speed applications by combining a very short arc length with very low spatter operation to provide industry-leading results on thin material. Rapid X<sup>®</sup> LS is a modification to this industry leading technology to adapt the Rapid X<sup>®</sup> waveform for the unique chemistry of low silicate wires like Lincoln Electric's SuperArc<sup>®</sup> XLS.

Rapid X<sup>®</sup> LS provides low spatter, high speed operation to deliver low silicate weld deposits that meet new industry standards for productivity, quality and weld appearance.



# RAPID X<sup>®</sup> LS



# Index

---

<b>Details</b> .....	2
Waveform .....	
<b>Optimization</b> .....	3
Synergic Welding .....	
Trim .....	
UltimArc <sup>®</sup> .....	
<b>Applications</b> .....	4-9
Flat Lap Weld Procedures .....	
2F/PB T-Joint Weld Procedures .....	
2F/PB Lap Weld Procedures .....	
<b>Set-up</b> .....	10-12
Sense Leads .....	
Work Leads .....	
Troubleshooting .....	
<b>Glossary</b> .....	13
Icons .....	
Technical Terms .....	
Procedure Notes .....	
Customer Assistance Policy .....	

RAPID X<sup>®</sup> LS


# Waveform



1

### PULSE RAMP/PEAK


A rapid current increase creates a molten droplet.



2

### TAILOUT


Reduced current relaxes the plasma force as the droplet approaches the puddle.



3

### WET-IN

Proprietary hardware quickly reduces the current at the instant the droplet contacts the puddle, reducing spatter after the droplet detaches.



4

### PUDDLE REPULSION

A plasma boost pushes the puddle away, creating separation and a stable rhythm of the weld pool.

# Optimization


## Synergic Welding

1. Adjust WFS to obtain proper fill rate at desired travel speed [See applications section for recommended settings].




## TRIM

2. Adjusting Trim increases or decreases the arc length, allowing the user to fine tune arc characteristics. Based on WFS, a pre-programmed nominal voltage is selected.



## ULTIMARC<sup>®</sup>

3. The UltimArc<sup>®</sup> control adjusts the pulse frequency to fine tune droplet transfer. It can be used to modify arc focus for varied welding positions and joint configurations.







**RAPID X<sup>®</sup> LS**

# Flat Lap Weld Procedures

Imperial

PLAIN CARBON STEEL	
Travel Angle	10-20°
Work Angle	25°-35°



FRONT SIDE SIDE  
 Ø - POSITION THE WIRE APPROXIMATELY ONE WIRE DIAMETER OUTSIDE THE JOINT.

**Imperial**

90AR / 10CO <sub>2</sub> 1/2 in	Material Thickness	Travel Speed in/min	Wire Feed Speed in/min	T	A	V
SuperArc <sup>®</sup> XLS 0.035 in	0.9 mm	45	200	1.00	98	19.8
	1.2 mm	45	300	1.00	139	21.1
	1.4 mm	45	350	1.00	156	21.7
	1.9 mm	45	450	1.00	193	23.1
	2.6 mm	45	630	0.95	252	24.0

**Imperial**

90AR / 10CO <sub>2</sub> 3/4 in	Material Thickness	Travel Speed in/min	Wire Feed Speed in/min	T	A	V
SuperArc <sup>®</sup> XLS 0.045 in	1.4 mm	45	215	1.00	148	20.8
	1.9 mm	45	330	1.00	218	22.6
	2.6 mm	45	440	1.00	281	24.8
	3.3 mm	45	510	1.00	320	26.2
	3.8 mm	45	560	1.00	341	27.2

**Imperial**

90AR / 10CO <sub>2</sub> 5/8 in	Material Thickness	Travel Speed in/min	Wire Feed Speed in/min	T	A	V
SuperArc <sup>®</sup> XLS 0.040 in	1.2 mm	45	215	1.00	112	20.5
	1.4 mm	45	260	1.00	134	21.1
	1.9 mm	45	385	1.00	190	22.8
	2.6 mm	45	500	1.00	234	24.3
	3.3 mm	45	580	1.00	261	25.3

Material Thickness | 
 Travel Speed | 
 Wire Feed Speed | 
 T Trim | 
 A Workpoint in Amps | 
 V Trim in Volts





See Customer Assistance Policy and Disclaimer Notice on page 13.

# RAPID X<sup>®</sup> LS

# Flat Lap Weld Procedures

Metric

PLAIN CARBON STEEL	
Travel Angle	10-20°
Work Angle	25°-35°



FRONT SIDE SIDE  
 Ø - POSITION THE WIRE APPROXIMATELY ONE WIRE DIAMETER OUTSIDE THE JOINT.

APPLICATIONS

## Metric

90AR / 10CO <sub>2</sub>				T	A	V
15 mm		cm/min	m/min			
	1.2 mm	114	5.46	1.00	112	20.5
	1.4 mm	114	6.60	1.00	134	21.1
	1.9 mm	114	9.78	1.00	190	22.8
	2.6 mm	114	12.70	1.00	234	24.3
	3.3 mm	114	14.73	1.00	261	25.3

## Metric

90AR / 10CO <sub>2</sub>				T	A	V
15 mm		cm/min	m/min			
	1.4 mm	114	5.08	1.00	163	21.0
	1.9 mm	114	7.62	1.00	229	21.9
	2.6 mm	114	9.53	1.00	283	23.5
	3.3 mm	102	12.70	1.00	358	26.0
	3.8 mm	102	13.46	0.95	374	25.3

## Metric

80AR / 20CO <sub>2</sub>				T	A	V
15 mm		cm/min	m/min			
	1.2 mm	114	5.46	1.00	115	23.1
	1.4 mm	114	6.60	1.00	130	23.5
	1.9 mm	114	9.78	1.00	182	25.5
	2.6 mm	114	12.70	1.00	234	27.4
	3.3 mm	114	14.73	1.00	256	28.7

## Metric

80AR / 20CO <sub>2</sub>				T	A	V
15 mm		cm/min	m/min			
	1.4 mm	114	5.08	1.00	160	24.5
	1.9 mm	114	7.62	1.00	221	26.0
	2.6 mm	114	9.91	0.98	284	27.9
	3.3 mm	102	12.07	0.90	329	27.7
	3.8 mm	102	12.70	0.90	340	28.1

Material Thickness | Travel Speed | Wire Feed Speed | T Trim | A Workpoint in Amps | V Trim in Volts


See Customer Assistance Policy and Disclaimer Notice on page 13.

# RAPID X<sup>®</sup> LS

# 2F/PB T-Joint Weld Procedures

Imperial

PLAIN CARBON STEEL	
Travel Angle	10-20°
Work Angle	40°-50°



## Imperial

90AR / 10CO <sub>2</sub>				T	A	V
1/2 in		in/min	in/min			
	0.9 mm	45	215	0.95	105	19.0
	1.2 mm	45	300	0.95	139	20.1
	1.4 mm	45	385	0.95	169	21.1
	1.9 mm	40	450	0.95	193	22.0
	2.6 mm	40	570	0.95	229	23.3

## Imperial

90AR / 10CO <sub>2</sub>				T	A	V
3/4 in		in/min	in/min			
	1.4 mm	45	240	1.00	166	21.2
	1.9 mm	45	310	0.95	205	21.0
	2.6 mm	45	430	0.95	274	23.4
	3.3 mm	40	430	0.95	274	23.4
	3.8 mm	40	450	0.95	288	23.8

## Imperial

90AR / 10CO <sub>2</sub>				T	A	V
5/8 in		in/min	in/min			
	1.2 mm	45	220	0.95	115	19.6
	1.4 mm	45	260	0.95	134	20.1
	1.9 mm	45	420	0.93	202	21.7
	2.6 mm	40	420	0.95	202	22.1
	3.3 mm	40	600	0.95	269	24.2

Material Thickness | Travel Speed | Wire Feed Speed | **T** Trim | **A** Workpoint in Amps | **V** Trim in Volts


See Customer Assistance Policy and Disclaimer Notice on page 13.

# RAPID X<sup>®</sup> LS

## 2F/PB T-Joint Weld Procedures

Metric

PLAIN CARBON STEEL	
Travel Angle	10-20°
Work Angle	40°-50°



### Metric

90AR / 10CO <sub>2</sub>				T	A	V
15 mm		cm/min	m/min			
	1.2 mm	114	5.59	0.95	115	19.6
	1.4 mm	114	6.60	0.95	134	20.1
	1.9 mm	114	10.67	0.93	202	21.7
	2.6 mm	102	10.67	0.95	202	22.1
	3.3 mm	102	15.24	0.95	269	24.2

### Metric

90AR / 10CO <sub>2</sub>				T	A	V
15 mm		cm/min	m/min			
	1.4 mm	114	5.08	0.95	163	20.0
	1.9 mm	114	6.99	0.95	213	20.5
	2.6 mm	114	9.40	0.95	279	22.2
	3.3 mm	102	10.16	0.95	301	22.8
	3.8 mm	102	10.67	0.97	314	23.7

### Metric

80AR / 20CO <sub>2</sub>				T	A	V
15 mm		cm/min	m/min			
	1.2 mm	114	6.10	1.00	124	23.3
	1.4 mm	114	7.11	0.95	137	22.6
	1.9 mm	114	10.16	0.95	190	24.4
	2.6 mm	114	12.32	0.95	227	25.8
	3.3 mm	102	15.24	0.97	264	28.1

### Metric

80AR / 20CO <sub>2</sub>				T	A	V
15 mm		cm/min	m/min			
	1.4 mm	114	5.08	0.92	160	22.5
	1.9 mm	114	6.60	0.95	195	23.8
	2.6 mm	114	8.64	0.95	251	25.7
	3.3 mm	114	10.67	0.95	301	28.0
	3.8 mm	114	11.68	0.95	322	29.1

Material Thickness | Travel Speed | Wire Feed Speed | **T** Trim | **A** Workpoint in Amps | **V** Trim in Volts





See Customer Assistance Policy and Disclaimer Notice on page 13.

**RAPID X<sup>®</sup> LS**

# 2F/PB Lap Weld Procedures

Imperial

PLAIN CARBON STEEL	
Travel Angle	10-20°
Work Angle	25°-35°



FRONT

SIDE

SIDE

Ø - POSITION THE WIRE APPROXIMATELY ONE WIRE DIAMETER OUTSIDE THE JOINT.

APPLICATIONS

**Imperial**

90AR / 10CO <sub>2</sub> 1/2 in		in/min	in/min	T	A	V
 SuperArc <sup>®</sup> XLS 0.035	0.9 mm	45	180	1.00	88	19.5
	1.2 mm	45	300	1.00	139	21.1
	1.4 mm	45	340	0.97	153	20.9
	1.9 mm	45	500	0.95	208	22.6
	2.6 mm	45	650	0.93	258	23.7

**Imperial**

90AR / 10CO <sub>2</sub> 3/4 in		in/min	in/min	T	A	V
 SuperArc <sup>®</sup> XLS 0.045 in	1.4 mm	45	215	1.00	148	20.8
	1.9 mm	45	310	0.97	205	21.5
	2.6 mm	40	360	0.97	236	22.5
	3.3 mm	40	420	0.97	268	23.7
	3.8 mm	40	500	0.97	316	25.2

**Imperial**

90AR / 10CO <sub>2</sub> 5/8 in		in/min	in/min	T	A	V
 SuperArc <sup>®</sup> XLS 0.040 in	1.2 mm	45	280	1.00	145	21.4
	1.4 mm	45	340	1.00	172	22.2
	1.9 mm	45	360	1.00	180	22.5
	2.6 mm	45	500	1.00	234	24.3
	3.3 mm	45	550	1.00	250	25.0



Material Thickness |



Travel Speed |



Wire Feed Speed | T Trim | A Workpoint in Amps | V Trim in Volts





See Customer Assistance Policy and Disclaimer Notice on page 13.

**RAPID X<sup>®</sup> LS**

# 2F/PB Lap Weld Procedures

Metric

PLAIN CARBON STEEL	
Travel Angle	10-20°
Work Angle	25°-35°



**FRONT SIDE SIDE**  
∅ - POSITION THE WIRE APPROXIMATELY ONE WIRE DIAMETER OUTSIDE THE JOINT.

APPLICATIONS

**Metric**

90AR / 10CO <sub>2</sub>				T	A	V
15 mm						
	1.2 mm	114	711	1.00	145	21.4
	1.4 mm	114	8.64	1.00	172	22.2
	1.9 mm	114	9.14	1.00	180	22.5
	2.6 mm	114	12.70	1.00	234	24.3
	3.3 mm	114	13.97	1.00	250	25.0

**Metric**

90AR / 10CO <sub>2</sub>				T	A	V
15 mm						
	1.4 mm	114	4.32	0.95	140	19.6
	1.9 mm	114	6.86	0.97	209	20.9
	2.6 mm	114	10.16	0.97	301	23.3
	3.3 mm	102	10.16	0.97	301	23.3
	3.8 mm	102	12.19	0.97	348	24.8

**Metric**

80AR / 20CO <sub>2</sub>				T	A	V
15 mm						
	1.2 mm	114	5.46	1.00	115	23.1
	1.4 mm	114	6.60	1.00	130	23.5
	1.9 mm	114	9.78	1.00	182	25.5
	2.6 mm	114	12.70	1.00	234	27.4
	3.3 mm	114	14.22	1.00	249	28.4

**Metric**

80AR / 20CO <sub>2</sub>				T	A	V
15 mm						
	1.4 mm	114	4.06	0.97	134	23.0
	1.9 mm	114	6.60	1.00	195	25.0
	2.6 mm	114	8.64	0.98	251	26.5
	3.3 mm	102	10.80	0.95	304	28.1
	3.8 mm	102	12.07	0.90	329	27.7

Material Thickness | Travel Speed | Wire Feed Speed | **T** Trim | **A** Workpoint in Amps | **V** Trim in Volts


See Customer Assistance Policy and Disclaimer Notice on page 13.

# RAPID X<sup>®</sup> LS

## Set-Up

### Sense Leads


A work sense lead (optional) is highly recommended for total welding cable lengths >50 ft. For best performance, connect the work sense lead close to the welding arc.



**DO NOT** connect the sense lead to a welding stud on the power source as this may result in erratic arc behavior.




The work sense lead should be separated away from welding cables to minimize interference.




### Work Leads

Connect the work lead to the negative stud on the power source and directly to the workpiece. Maintain the shortest connection length possible.







Test cable inductance levels using the Power Wave<sup>®</sup> Manager software exclusively from Lincoln Electric<sup>®</sup> Software. Available at [www.powerwavesoftware.com](http://www.powerwavesoftware.com).



The total length of the welding current loop (A+B+C) should be minimized to reduce inductance. Route cables (A,B) close together to further reduce cable inductance.



# Troubleshooting

 <p>Spatter</p>	Check ▶	 <p>Trim/Volts</p>	 <p>Travel Speed</p>	 <p>Wire Feed Speed</p>	 <p>Gas Coverage</p>	 <p>Push Angle</p>	 <p>UltimArc<sup>®</sup></p>	 <p>Work Sense Lead</p>
	Action ▶							




 <p>Erratic Arc</p>	Check ▶	 <p>Proper Feeding</p>	 <p>Contact Tip</p>	 <p>Travel Speed</p>	 <p>Trim/Volts</p>	 <p>Wire Feed Speed</p>	 <p>Work Sense Lead</p>
	Action ▶						




 <p>Porosity</p>	Check ▶	 <p>Gas Coverage</p>	 <p>Proper Feeding</p>	 <p>Contact Tip to Work Distance</p>	 <p>Travel Speed</p>
	Action ▶				





 <p>Concave Bead</p>	Check ▶	 <p>Trim/Volts</p>	 <p>Wire Feed Speed</p>	 <p>Travel Speed</p>
	Action ▶			

	Check Parameters
	Increase
	Decrease
	Inspect & Replace
	Important

# Troubleshooting

 Burnthrough	Check ▶	 Travel Speed	 Wire Feed Speed	<b>T/V</b> Trim/Volts	 Contact Tip to Work Distance	 Push Angle
	Action ▶					



 Convex Bead	Check ▶	<b>T/V</b> Trim/Volts	 Wire Feed Speed	 Push Angle	 Contact Tip to Work Distance	 Travel Speed
	Action ▶					

 Poor Penetration	Check ▶	 Travel Speed	 Wire Feed Speed	 UltimArc <sup>®</sup>	 Contact Tip to Work Distance	 Push Angle
	Action ▶					

	Check Parameters
	Increase
	Decrease
	Inspect & Replace
	Important

# Glossary

## Icons

 Wire Type	 Gas	 Material Thickness	 Wire Feed Speed	 Travel Speed	<b>V</b> Trim in Volts	<b>A</b> Workpoint in Amps	 UltimArc <sup>®</sup>	 Contact Tip to Work Distance	 Push Angle
 Control Knob	 Weld Stud	 Torch	 Work Sense Lead	 Work Clamp	 Torch Nozzle	 Spatter	 Erratic Arc	 Proper Feeding	 Arc Length
<b>T</b> Trim	 Gas Coverage	 Porosity	 Concave Bead	 Burnthrough	 Under Cut	 Convex Bead	 Poor Penetration	 Stop/Avoid	

## Technical Terms

**Cable Inductance** – Resistance to change in current.

**GMAW** – Gas metal arc welding including metal inert gas (MIG) and metal active gas (MAG) welding.

**Porosity** – Spherical or elongated entrapments of gas in solidified weld metal.

**Travel Angle** – The angle of the welding torch relative to the direction of travel.

**Synergic** – A mode of control which automatically selects a preprogrammed nominal voltage based on the wire feed speed (WFS) set by the operator.

**Work Angle** – The angle of the electrode, off perpendicular, relative to the work piece surface.

## Procedure Notes

All listed procedures are starting points and may require some adjustment depending on the specific application. Torch angle, electrode placement, contamination, mill scale, joint fit up, and joint consistency are factors that may require special consideration depending on the specific application. At higher travel speeds, joint fit up, wire placement, and contamination all become factors that are more significant. The result of welding at higher travel speeds is a tendency to produce more spatter, less penetration, more undercut, and a less desirable bead shape. Depending on the limitations / requirements of the actual application, slower travel speeds and higher arc voltages may be required. As the travel speed increases in fast follow applications (1/4" to 1/4 Gauge), a tighter arc length must be maintained so that the puddle properly follows the arc. Operators typically reduce the arc length control (Trim) to achieve this. At faster travel speeds, the bead-shape can become very convex (or ropy), and the weld will not "wet" well. There is a point at which the arc is set so short that the arc will become unstable and stubbing will occur. This forms a limitation of just how fast the travel speed can be raised. It is ultimately the responsibility of the end user to ensure the proper weld deposition rate, bead profile, and structural integrity of a given weld application.

CUSTOMER ASSISTANCE POLICY The Lincoln Electric Company is manufacturing and selling high quality welding equipment, consumables, and cutting equipment. Our challenge is to meet the needs of our customers and to exceed their expectations. On occasion, purchasers may ask Lincoln Electric for information or advice about their use of our products. Our employees respond to inquiries to the best of their ability based on information provided to them by the customers and the knowledge they may have concerning the application. Our employees, however, are not in a position to verify the information provided or to evaluate the engineering requirements for the particular weldment. Accordingly, Lincoln Electric does not warrant or guarantee or assume any liability with respect to such information or advice. Moreover, the provision of such information or advice does not create, expand, or alter any warranty on our products. Any express or implied warranty that might arise from the information or advice, including any implied warranty of merchantability or any warranty of fitness for any customers' particular purpose is specifically disclaimed.

Lincoln Electric is a responsive manufacturer, but the selection and use of specific products sold by Lincoln Electric is solely within the control of, and remains the sole responsibility of the customer. Many variables beyond the control of Lincoln Electric affect the results obtained in applying these types of fabrication methods and service requirements.

Subject to Change – This information is accurate to the best of our knowledge at the time of printing. Please refer to [www.lincolnelectric.com](http://www.lincolnelectric.com) for any updated information.

All trademarks and registered trademarks are the property of their respective owners.