

Operator's Manual

MAGNUM[®] 500

Gun & Cable Assemblies



For use with machines having Code Numbers:

K574

K1722

IEC 60974-7

GB 15579.7: 2013



Register your machine:

www.lincolnelectric.com/register

Authorized Service and Distributor Locator:

www.lincolnelectric.com/locator

Save for future reference

Date Purchased

Code: (ex: 10859)

Serial: (ex: U1060512345)

THANK YOU FOR SELECTING A QUALITY PRODUCT BY LINCOLN ELECTRIC.

PLEASE EXAMINE CARTON AND EQUIPMENT FOR DAMAGE IMMEDIATELY

When this equipment is shipped, title passes to the purchaser upon receipt by the carrier. Consequently, claims for material damaged in shipment must be made by the purchaser against the transportation company at the time the shipment is received.

SAFETY DEPENDS ON YOU

Lincoln arc welding and cutting equipment is designed and built with safety in mind. However, your overall safety can be increased by proper installation ... and thoughtful operation on your part. **DO NOT INSTALL, OPERATE OR REPAIR THIS EQUIPMENT WITHOUT READING THIS MANUAL AND THE SAFETY PRECAUTIONS CONTAINED THROUGHOUT.** And, most importantly, think before you act and be careful.

WARNING

This statement appears where the information must be followed exactly to avoid serious personal injury or loss of life.

CAUTION

This statement appears where the information must be followed to avoid minor personal injury or damage to this equipment.



KEEP YOUR HEAD OUT OF THE FUMES.

DON'T get too close to the arc. Use corrective lenses if necessary to stay a reasonable distance away from the arc.


READ and obey the Safety Data Sheet (SDS) and the warning label that appears on all containers of welding materials.

USE ENOUGH VENTILATION or exhaust at the arc, or both, to keep the fumes and gases from your breathing zone and the general area.

IN A LARGE ROOM OR OUTDOORS, natural ventilation may be adequate if you keep your head out of the fumes (See below).

USE NATURAL DRAFTS or fans to keep the fumes away from your face.

If you develop unusual symptoms, see your supervisor. Perhaps the welding atmosphere and ventilation system should be checked.



WEAR CORRECT EYE, EAR & BODY PROTECTION

PROTECT your eyes and face with welding helmet properly fitted and with proper grade of filter plate (See ANSI Z49.1).

PROTECT your body from welding spatter and arc flash with protective clothing including woolen clothing, flame-proof apron and gloves, leather leggings, and high boots.

PROTECT others from splatter, flash, and glare with protective screens or barriers.

IN SOME AREAS, protection from noise may be appropriate.

BE SURE protective equipment is in good condition.

Also, wear safety glasses in work area **AT ALL TIMES.**



SPECIAL SITUATIONS

DO NOT WELD OR CUT containers or materials which previously had been in contact with hazardous substances unless they are properly cleaned. This is extremely dangerous.

DO NOT WELD OR CUT painted or plated parts unless special precautions with ventilation have been taken. They can release highly toxic fumes or gases.

Additional precautionary measures

PROTECT compressed gas cylinders from excessive heat, mechanical shocks, and arcs; fasten cylinders so they cannot fall.

BE SURE cylinders are never grounded or part of an electrical circuit.

REMOVE all potential fire hazards from welding area.

ALWAYS HAVE FIRE FIGHTING EQUIPMENT READY FOR IMMEDIATE USE AND KNOW HOW TO USE IT.



SECTION A: WARNINGS



CALIFORNIA PROPOSITION 65 WARNINGS

Diesel Engines

Diesel engine exhaust and some of its constituents are known to the State of California to cause cancer, birth defects, and other reproductive harm.

Gasoline Engines

The engine exhaust from this product contains chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm.

ARC WELDING CAN BE HAZARDOUS. PROTECT YOURSELF AND OTHERS FROM POSSIBLE SERIOUS INJURY OR DEATH. KEEP CHILDREN AWAY. PACEMAKER WEARERS SHOULD CONSULT WITH THEIR DOCTOR BEFORE OPERATING.

Read and understand the following safety highlights. For additional safety information, it is strongly recommended that you purchase a copy of "Safety in Welding & Cutting - ANSI Standard Z49.1" from the American Welding Society, P.O. Box 351040, Miami, Florida 33135 or CSA Standard W117.2-1974. A Free copy of "Arc Welding Safety" booklet E205 is available from the Lincoln Electric Company, 22801 St. Clair Avenue, Cleveland, Ohio 44117-1199.

BE SURE THAT ALL INSTALLATION, OPERATION, MAINTENANCE AND REPAIR PROCEDURES ARE PERFORMED ONLY BY QUALIFIED INDIVIDUALS.



FOR ENGINE POWERED EQUIPMENT.

- 1.a. Turn the engine off before troubleshooting and maintenance work unless the maintenance work requires it to be running.



- 1.b. Operate engines in open, well-ventilated areas or vent the engine exhaust fumes outdoors.

- 1.c. Do not add the fuel near an open flame welding arc or when the engine is running. Stop the engine and allow it to cool before refueling to prevent spilled fuel from vaporizing on contact with hot engine parts and igniting. Do not spill fuel when filling tank. If fuel is spilled, wipe it up and do not start engine until fumes have been eliminated.



- 1.d. Keep all equipment safety guards, covers and devices in position and in good repair. Keep hands, hair, clothing and tools away from V-belts, gears, fans and all other moving parts when starting, operating or repairing equipment.



- 1.e. In some cases it may be necessary to remove safety guards to perform required maintenance. Remove guards only when necessary and replace them when the maintenance requiring their removal is complete. Always use the greatest care when working near moving parts.

- 1.f. Do not put your hands near the engine fan. Do not attempt to override the governor or idler by pushing on the throttle control rods while the engine is running.

- 1.g. To prevent accidentally starting gasoline engines while turning the engine or welding generator during maintenance work, disconnect the spark plug wires, distributor cap or magneto wire as appropriate.

- 1.h. To avoid scalding, do not remove the radiator pressure cap when the engine is hot.



ELECTRIC AND MAGNETIC FIELDS MAY BE DANGEROUS



- 2.a. Electric current flowing through any conductor causes localized Electric and Magnetic Fields (EMF). Welding current creates EMF fields around welding cables and welding machines
- 2.b. EMF fields may interfere with some pacemakers, and welders having a pacemaker should consult their physician before welding.
- 2.c. Exposure to EMF fields in welding may have other health effects which are now not known.
- 2.d. All welders should use the following procedures in order to minimize exposure to EMF fields from the welding circuit:
- 2.d.1. Route the electrode and work cables together - Secure them with tape when possible.
- 2.d.2. Never coil the electrode lead around your body.
- 2.d.3. Do not place your body between the electrode and work cables. If the electrode cable is on your right side, the work cable should also be on your right side.
- 2.d.4. Connect the work cable to the workpiece as close as possible to the area being welded.
- 2.d.5. Do not work next to welding power source.



ELECTRIC SHOCK CAN KILL.



- 3.a. The electrode and work (or ground) circuits are electrically “hot” when the welder is on. Do not touch these “hot” parts with your bare skin or wet clothing. Wear dry, hole-free gloves to insulate hands.
- 3.b. Insulate yourself from work and ground using dry insulation. Make certain the insulation is large enough to cover your full area of physical contact with work and ground.

In addition to the normal safety precautions, if welding must be performed under electrically hazardous conditions (in damp locations or while wearing wet clothing; on metal structures such as floors, gratings or scaffolds; when in cramped positions such as sitting, kneeling or lying, if there is a high risk of unavoidable or accidental contact with the workpiece or ground) use the following equipment:

- Semiautomatic DC Constant Voltage (Wire) Welder.
 - DC Manual (Stick) Welder.
 - AC Welder with Reduced Voltage Control.
- 3.c. In semiautomatic or automatic wire welding, the electrode, electrode reel, welding head, nozzle or semiautomatic welding gun are also electrically “hot”.
 - 3.d. Always be sure the work cable makes a good electrical connection with the metal being welded. The connection should be as close as possible to the area being welded.
 - 3.e. Ground the work or metal to be welded to a good electrical (earth) ground.
 - 3.f. Maintain the electrode holder, work clamp, welding cable and welding machine in good, safe operating condition. Replace damaged insulation.
 - 3.g. Never dip the electrode in water for cooling.
 - 3.h. Never simultaneously touch electrically “hot” parts of electrode holders connected to two welders because voltage between the two can be the total of the open circuit voltage of both welders.
 - 3.i. When working above floor level, use a safety belt to protect yourself from a fall should you get a shock.
 - 3.j. Also see Items 6.c. and 8.



ARC RAYS CAN BURN.



- 4.a. Use a shield with the proper filter and cover plates to protect your eyes from sparks and the rays of the arc when welding or observing open arc welding. Headshield and filter lens should conform to ANSI Z87.1 standards.
- 4.b. Use suitable clothing made from durable flame-resistant material to protect your skin and that of your helpers from the arc rays.
- 4.c. Protect other nearby personnel with suitable, non-flammable screening and/or warn them not to watch the arc nor expose themselves to the arc rays or to hot spatter or metal.




FUMES AND GASES CAN BE DANGEROUS.



- 5.a. Welding may produce fumes and gases hazardous to health. Avoid breathing these fumes and gases. When welding, keep your head out of the fume. Use enough ventilation and/or exhaust at the arc to keep fumes and gases away from the breathing zone. **When welding hardfacing (see instructions on container or SDS) or on lead or cadmium plated steel and other metals or coatings which produce highly toxic fumes, keep exposure as low as possible and within applicable OSHA PEL and ACGIH TLV limits using local exhaust or mechanical ventilation unless exposure assessments indicate otherwise. In confined spaces or in some circumstances, outdoors, a respirator may also be required. Additional precautions are also required when welding on galvanized steel.**
- 5.b. The operation of welding fume control equipment is affected by various factors including proper use and positioning of the equipment, maintenance of the equipment and the specific welding procedure and application involved. Worker exposure level should be checked upon installation and periodically thereafter to be certain it is within applicable OSHA PEL and ACGIH TLV limits.
- 5.c. Do not weld in locations near chlorinated hydrocarbon vapors coming from degreasing, cleaning or spraying operations. The heat and rays of the arc can react with solvent vapors to form phosgene, a highly toxic gas, and other irritating products.
- 5.d. Shielding gases used for arc welding can displace air and cause injury or death. Always use enough ventilation, especially in confined areas, to insure breathing air is safe.
- 5.e. Read and understand the manufacturer’s instructions for this equipment and the consumables to be used, including the Safety Data Sheet (SDS) and follow your employer’s safety practices. SDS forms are available from your welding distributor or from the manufacturer.
- 5.f. Also see item 1.b.




WELDING AND CUTTING SPARKS CAN CAUSE FIRE OR EXPLOSION.



- 6.a. Remove fire hazards from the welding area. If this is not possible, cover them to prevent the welding sparks from starting a fire. Remember that welding sparks and hot materials from welding can easily go through small cracks and openings to adjacent areas. Avoid welding near hydraulic lines. Have a fire extinguisher readily available.
- 6.b. Where compressed gases are to be used at the job site, special precautions should be used to prevent hazardous situations. Refer to "Safety in Welding and Cutting" (ANSI Standard Z49.1) and the operating information for the equipment being used.
- 6.c. When not welding, make certain no part of the electrode circuit is touching the work or ground. Accidental contact can cause overheating and create a fire hazard.
- 6.d. Do not heat, cut or weld tanks, drums or containers until the proper steps have been taken to insure that such procedures will not cause flammable or toxic vapors from substances inside. They can cause an explosion even though they have been "cleaned". For information, purchase "Recommended Safe Practices for the Preparation for Welding and Cutting of Containers and Piping That Have Held Hazardous Substances", AWS F4.1 from the American Welding Society (see address above).
- 6.e. Vent hollow castings or containers before heating, cutting or welding. They may explode.
- 6.f. Sparks and spatter are thrown from the welding arc. Wear oil free protective garments such as leather gloves, heavy shirt, cuffless trousers, high shoes and a cap over your hair. Wear ear plugs when welding out of position or in confined places. Always wear safety glasses with side shields when in a welding area.
- 6.g. Connect the work cable to the work as close to the welding area as practical. Work cables connected to the building framework or other locations away from the welding area increase the possibility of the welding current passing through lifting chains, crane cables or other alternate circuits. This can create fire hazards or overheat lifting chains or cables until they fail.
- 6.h. Also see item 1.c.
- 6.i. Read and follow NFPA 51B "Standard for Fire Prevention During Welding, Cutting and Other Hot Work", available from NFPA, 1 Batterymarch Park, PO box 9101, Quincy, MA 02269-9101.
- 6.j. Do not use a welding power source for pipe thawing.



CYLINDER MAY EXPLODE IF DAMAGED.

- 7.a. Use only compressed gas cylinders containing the correct shielding gas for the process used and properly operating regulators designed for the gas and pressure used. All hoses, fittings, etc. should be suitable for the application and maintained in good condition. 
- 7.b. Always keep cylinders in an upright position securely chained to an undercarriage or fixed support.
- 7.c. Cylinders should be located:
 - Away from areas where they may be struck or subjected to physical damage.
 - A safe distance from arc welding or cutting operations and any other source of heat, sparks, or flame.
- 7.d. Never allow the electrode, electrode holder or any other electrically "hot" parts to touch a cylinder.
- 7.e. Keep your head and face away from the cylinder valve outlet when opening the cylinder valve.
- 7.f. Valve protection caps should always be in place and hand tight except when the cylinder is in use or connected for use.
- 7.g. Read and follow the instructions on compressed gas cylinders, associated equipment, and CGA publication P-1, "Precautions for Safe Handling of Compressed Gases in Cylinders," available from the Compressed Gas Association, 14501 George Carter Way Chantilly, VA 20151.



FOR ELECTRICALLY POWERED EQUIPMENT.



- 8.a. Turn off input power using the disconnect switch at the fuse box before working on the equipment.
- 8.b. Install equipment in accordance with the U.S. National Electrical Code, all local codes and the manufacturer's recommendations.
- 8.c. Ground the equipment in accordance with the U.S. National Electrical Code and the manufacturer's recommendations.

Refer to
<http://www.lincolnelectric.com/safety>
for additional safety information.

Installation	Section A
General Description	A-1, A-2
Connector Kit Installation to Gun Cable	A-3
K613-1 & -6 Installation (for Lincoln Feeders)	A-3
K613-2 Installation (for Tweco® Adapted and Lincoln DH-10, LN-10, PF-10 & STT-10 Feeders) ..	A-3
K613-3 Installation (for Miller® Feeders)	A-3
K613-4 Installation (for Older Hobart® Feeders)	A-4
K613-5 Installation (for Hobart® Series 2000 Feeders)	A-4
Liner Installation and Trimming Instructions	A-4
Rotating the Gun Tube	A-5
Contract Tip and Gas Nozzle Installation	A-5
Connection to Feeder	A-5
Connection to Lincoln Feeders	A-5
Connection to Tweco Adapted and Lincoln DH-10, LN-10, PF-10 & STT-10 Feeders ..	A-5
Connection to Miller Feeders	A-5
Connection to Older Hobart Feeders	A-6
Connection to Hobart Series 2000 Feeders	A-6
Installation of Optional Gun Hanger	A-6

Operation	Section B
Electrodes and Equipment	B-1
Making a Weld	B-1
Avoiding Wire Feeding Problems	B-1

Maintenance	Section D
Removal, Installation and Trimming Instructions for MAGNUM® Liners	D-1
Gun Tubes and Nozzles	D-1
Gun Cables	D-1
Cable Cleaning	D-1
Cable Repair	D-1
Gun Tube End Repair	D-1, D-2
Wire Feeder End Repair	D-3
Thread Sizes for MAGNUM® 550 Consumables	D-4

Troubleshooting	Section E
------------------------------	------------------

Parts Lists	P-202-P
--------------------------	----------------

GENERAL DESCRIPTION

The MAGNUM® 550 GMA gun and cable assembly has been designed to meet NEMA specification EW3 for welding with steel electrode using the GMAW (gas metal arc welding) and the gas-shielded FCAW (flux-cored arc welding) processes:

MAGNUM™ 550
500 AMPS AT 60% DUTY CYCLE WITH CO₂ GAS
500 AMPS AT 40% DUTY CYCLE WITH MIXED GAS

Product Number	Gun Cable Length ft. (m)	Wire Size in. (mm)	Contact Tips	Gas Diffuser	Coarse Thread Nozzle	Coarse Thread Nozzle Insulator Assembly	Cable Liner	Gun Tube 60°
K598-1	10ft. (3.0m)	.035" (0.9mm) .045" (1.2mm)	KP16S-35 KP16S-45	KP56S-SW	KP26CT-62 .625 I.D. .12 Rec.	KP36CT	KP45-3545-15	KP1951-1
K598-2	12 ft. (3.6m)	.035" (0.9mm) .045" (1.2mm)	KP16S-35 KP16S-45	KP56S-SW	KP26CT-62 .625 I.D. .12 Rec.	KP36CT	KP45-3545-15	KP1951-1
K598-3	15 ft. (4.5m)	.035" (0.9mm) .045" (1.2mm)	KP16S-35 KP16S-45	KP56S-SW	KP26CT-62 .625 I.D. .12 Rec.	KP36CT	KP45-3545-15	KP1951-1
K598-4	25 ft. (7.5m)	.035" (0.9mm) .045" (1.2mm)	KP16S-35 KP16S-45	KP56S-SW	KP26CT-62 .625 I.D. .12 Rec.	KP36CT	KP45-3545-25	KP1951-1
K598-5	10 ft. (3.0m)	.052" (1.3mm) 1/16" (1.6mm)	KP16S-52 KP16S-116	KP56S-SW	KP26CT-62 .625 I.D. .12 Rec.	KP36CT	KP45-116-15	KP1951-1
K598-6	12 ft. (3.6m)	.052" (1.3mm) 1/16" (1.6mm)	KP16S-52 KP16S-116	KP56S-SW	KP26CT-62 .625 I.D. .12 Rec.	KP36CT	KP45-116-15	KP1951-1
K598-7	15 ft. (4.5m)	.052" (1.3mm) 1/16" (1.6mm)	KP16S-52 KP16S-116	KP56S-SW	KP26CT-62 .625 I.D. .12 Rec.	KP36CT	KP45-116-15	KP1951-1
K598-8	25 ft. (7.5m)	.052" (1.3mm) 1/16" (1.6mm)	KP16S-52 KP16S-116	KP56S-SW	KP26CT-62 .625 I.D. .12 Rec.	KP36CT	KP45-116-25	KP1951-1
K598-9	10 ft. (3.0m)	5/64" (2.0mm) 3/32" (2.4mm)	KP16S-564 KP16S-332	KP56S-H	KP26CT-75-R .750 I.D. .25 Rec.	KP36CT	KP45H-332-15	KP1951-2
K598-10	12 ft. (3.6m)	5/64" (2.0mm) 3/32" (2.4mm)	KP16S-564 KP16S-332	KP56S-H	KP26CT-75-R .750 I.D. .25 Rec.	KP36CT	KP45H-332-15	KP1951-2
K598-11	15 ft. (4.5m)	5/64" (2.0mm) 3/32" (2.4mm)	KP16S-564 KP16S-332	KP56S-H	KP26CT-75-R .750 I.D. .25 Rec.	KP36CT	KP45H-332-15	KP1951-2
K598-12	10 ft. (3.0m)	7/64" (2.8mm) 1/8" (3.2mm)	KP16S-764 KP16S-18	KP56S-H	KP26CT-75-R .750 I.D. .25 Rec.	KP36CT	KP45-18-15	KP1951-2
K598-13	12 ft. (3.6m)	7/64" (2.8mm) 1/8" (3.2mm)	KP16S-764 KP16S-18	KP56S-H	KP26CT-75-R .750 I.D. .25 Rec.	KP36CT	KP45-18-15	KP1951-2
K598-14	15 ft. (4.5m)	7/64" (2.8mm) 1/8" (3.2mm)	KP16S-764 KP16S-18	KP56S-H	KP26CT-75-R .750 I.D. .25 Rec.	KP36CT	KP45-18-15	KP1951-2
K598-15	15 ft. (4.5m)	.035" (0.9mm)	KP15H-35 KP15H-45	KP55SW	KP25CT-62 .62 I.D. .12 Rec.	KP35CT	KP45-3545-15	KP1951-3
K598-16	15 ft. (4.5m)	.052" (1.3mm) 1/16" (1.6mm)	KP15H-53 KP15H-116	KP55SW	KP25CT-62 .62 I.D. .12 Rec.	KP35CT	KP45-116-15	KP1951-3
K598-17	15 ft. (4.5m)	5/64" (2.0mm) 3/32" (2.4mm)	KP15H-564 KP15H-332	KP55H	KP25CT-75 .75 I.D. .12 Rec.	KP35CT	KP45H-332-15	KP1951-3
K598-18	15 ft. (4.5m)	7/64" (2.8mm) 1/8" (3.2mm)	KP15H-764 KP15H-18	KP55-H	KP25CT-75 .75 I.D. .12 Rec.	KP35CT	KP45-18-15	KP1951-3



The K598 MAGNUM® guns are not factory equipped with a feeder end connector. With the K613-1 MAGNUM® Connector Kit, they can be used with any Lincoln LN-7 or LN-25 semiautomatic wire feeder. The K613-1 can also be used with the LN-8 or LN-9 when feeding .052 and smaller electrodes. For additional Connector Kits see the "P-202 ACCESSORIES" section of this manual. An optional K481 MAGNUM® Fast-Connect Gas Tube Kit is available to provide tool-less gas tube connection to Lincoln wire feeders. Non-GMA model wire feeders require an optional gas solenoid valve.

An interlocking trigger is available as a parts order. With the trigger pulled in all the way, the trigger can be slid forward into the interlock position. To release interlock, squeeze trigger and slide back. The trigger is made of a spatter resistant material. See the "P-202 ACCESSORIES" section of this manual.

For best results when welding mild and alloy steels, it is recommended that L-50 or L-56 Lincoln solid wire electrodes be used for the GMAW process and Lincoln Outershield® cored electrodes for the gas-shielded FCAW process.

Liners are available for feeding the harder (5356) 3/64" or 1/16" aluminum electrode. The liners have a flat spring steel jacket with a frictionless core. Although these liners are provided in 15 ft. lengths, 10 ft. cable lengths are recommended to reduce feeding problems. See the "P-202 ACCESSORIES" section of this manual.

INSTALLATION

WARNING

ELECTRIC SHOCK can kill.

- Have a qualified individual install and service this equipment.



- Turn the input power for the power source off at the fuse box or disconnect switch before working on this equipment.

- Do not touch electrically hot parts such as output terminals or internal wiring.

CONNECTOR KIT INSTALLATION TO GUN CABLE

The K598 MAGNUM® 550 Guns and Cables are shipped as "generic" and must be assembled with either a K613-1 Lincoln Connection Kit for standard Lincoln wire feeders (LN-8 or LN9 using smaller than 1/16 electrode), a K613-2 Tweco Adapted Feeder Connection Kit for wire feeders adapted for use with comparable size Tweco gun cables, a K613-3 Connector Kit for a variety of Miller wire feeders, a K613-4 Connector Kit for a variety of older Hobart wire feeders, a K613-5 Connector Kit for Hobart Series 2000 wire feeders and K613-6 Connector Kit for LN-8 or LN-9 wire feeders using 1/16 and larger electrode. Each of the above connections are covered below. You may skip to the instructions that are appropriate for your wire feeder.

K613-1 & K613-6 Installation (For Lincoln Feeders)

- Remove brass cable connector and insulation tube (See Figure 1) from the K613-1 kit. Slide the insulation tube onto the connector from the threaded end and screw it onto the feeder end of the gun cable. Tighten the connection.
- Remove the molded gas plug fitting on the side of the feeder end handle and replace it with the barbed brass fitting provided in the kit.
- Attach the round connector of the gun control cable provided to the trigger connector on the front of the Lincoln feeder.

NOTE: Both the plug and socket are keyed and must be properly oriented.

- Place one tubing clamp onto each end of the flexible tubing provided, approximately 2" (51mm) in from each end. Slide one end of the tubing onto the barbed connector on the feeder end cable handle (step b) and move the clamp down near the end of the tube to assure a good gas seal.

NOTE: An optional K481 MAGNUM® Fast-Connect Gas Tube Kit is available to provide tool-less gas tube connection to Lincoln wire feeders. Install per the instructions sent with the kit.

K613-2 Installation (For Tweco Adapted Feeders and Lincoln DH-10, LN-10, PF-10 and STT-10)

- Remove brass cable connector (See Figure 1) from the K613-2 kit and screw it onto the feeder end of the gun cable. Tighten the connection.
- Check that the molded gas plug fitting is sealing the gas fitting hole in the side of the feeder end handle.

K613-3 Installation (For Miller Feeders)

- Remove brass cable connector (See Figure 1) from the K613-3 kit and screw it on to the feeder end of the gun cable. Tighten the connection.
- Check that the molded gas plug fitting is sealing the gas fitting hole in the side of the feeder end handle.
- Attach the round connector of the gun control cable provided to the trigger connector on the front of the Miller feeder.


K613-4 Installation (For Older Hobart Feeders)

- a. Remove brass cable connector (See Figure 1) from the K613-4 kit and screw it on to the feeder end of the gun cable. Tighten the connector.
- b. Remove the molded gas plug fitting on the side of the feeder end handle and replace it with the barbed brass fitting provided in the kit.
- c. Attach the phone plug connector of the gun control cable provided to the trigger connector on the front of the Hobart feeder.
- d. Place one tubing clamp onto each end of the flexible tubing provided, approximately 2" (51mm) in from each end.

Slide one end of the tubing onto the barbed connector on the feeder end cable handle (step b) and move the clamp down near the end of the tube to assure a good gas seal.

K613-5 Installation (For Hobart Series 2000 Wire Feeders)

- a. Remove brass cable connector (see Figure 1) from the K613-5 kit and screw it onto the feeder end of the gun cable. Tighten the connection.
- b. Check that the molded gas plug fitting is sealing the gas fitting hole in the side of the feeder end handle.
- c. Attach the Gun Control cable provided to the trigger connector on the front of the wire feeder.



Gun	Diffuser	Liner cut off length
K598-1 thru -14	KP56S-SW, KP56S-H	.38" (9.5mm)
K598-15 thru -18	KP55SW, KP55, KP55H, KP55S-SW, KP55S-H	.50" (12.7mm)
K598-15 thru -18	KP55S-SWL, KP55S-HL	1.00" (25.4mm)

Figure 1

LINER INSTALLATION AND TRIMMING INSTRUCTIONS

- a. Lay the gun and cable out straight on a flat surface.
- b. Make sure that the set screws in the connector end and in the handle are backed out so as not to damage liner or liner bushing. Remove and save the coarse thread nozzle and coarse thread insulator assembly from the end of the gun tube assembly.
- c. Insert a new untrimmed liner into the connector end of the cable. Be sure the liner bushing is stencilled appropriately for the wire size being used.

NOTE: For liners KP45N-3545-15, KP45N-116-15, gun tube assemblies KP1951-1 and KP1951-2. Before fully seating the liner bushing, it will be necessary to trim the liner's inner tube flush with the liner bushing using a sharp blade. After trimming remove any burrs from inner tube and insure that the opening is fully open.

- d. Before installing the gas diffuser, fully seat the liner bushing in the connector and:

For K613-1, K613-2, K613-5 and K613-6, tighten the set screw in the cable connector.

OR

For K613-3 and K613-4, screw in the connector cap provided in the kit until it seats on the face of the bushing. Then insert the appropriate piece of liner material into the connector cap and tighten the set screw. Four pieces of liner material are included in these connector kits to help guide the electrode through the connector cap. The piece with the smallest inner diameter is designed for .045" (1.2mm) maximum diameter electrode. The next largest diameter is for 1/16" (1.6mm) maximum diameter electrode. The largest diameter piece of liner material is for 1/8" (3.2mm) maximum diameter electrode. The next largest is for 3/32" (2.4mm) maximum diameter electrode.

- e. Be sure the cable is straight and then trim the liner to the length shown in Figure 1. Remove any burrs from the end of the liner.
- f. Screw the gas diffuser onto the end of the gun tube and tighten. Be sure to use the proper diffuser size for the electrode being used.
- g. For K598-1 thru -14: Tighten the set screw in the side of the gun handle against the cable liner. For K598-15 thru -18: Tighten the set screw in the diffuser against the cable liner.

CAUTION

This screw should only be gently tightened. Over-tightening will split or collapse the liner and cause poor wire feeding.

ROTATING THE GUN TUBE

The gun tube can be rotated to any position desired by the operator. Loosen the clamping screw, rotate the gun tube to the desired position and retighten the clamping screw. The gun can be operated with the trigger on top. Simply rotate the gun tube 180° and operate the gun with the trigger on top.

CONTACT TIP AND GAS NOZZLE INSTALLATION

- a. Choose the correct size contact tip for the electrode being used (wire size is stenciled on the side of the contact tip) and screw it snugly into the gas diffuser.
- b. Be sure the coarse thread insulator assembly is fully screwed onto the gun tube and does not block the gas holes in the diffuser.

NOTE: The coarse thread insulator assembly is not required when using the optional self insulated gas nozzles.

- c. Screw the appropriate coarse thread nozzle onto the coarse thread insulator assembly. Coarse thread nozzles are available with a .62" (15.9mm) or .75" (19.1mm) I.D., and in both 1/8" recessed and 1/4" recessed design.

The proper nozzle should be selected based on the welding application. Different diameter self insulated gas nozzles are also available to allow gas-shielded, flux-cored welding. .62" (15.9mm). .75" (19.1mm) and .88" (22.4mm) diameter nozzles are available. The self insulated gas nozzles provide a tip recess of 1/8".

Choose the gas nozzle as appropriate for the GMAW process to be used. Typically, the contact tip end should be 1/8" (3 mm) recessed for spray transfer and for the Outershield® (FCAW) process.

CONNECTION TO FEEDER

Connection to Lincoln Feeders

Gun cable assemblies which were assembled with a **K613-1** or **K613-6** Connection Kit will connect easily to any Lincoln LN-7, LN-8, LN-9 or LN-25 feeder.

- a. Check that the drive roll(s) and feeder guide tubes are appropriate for the electrode size being used.
- b. Fully push the brass connector end of the gun cable into the conductor block on the outgoing side of the feeder wire drive. Secure the cable using the hand screw or set screw in the conductor block.
- c. Insert the control cable plug from the feeder trigger circuit into the mating socket on the feeder end cable handle.
- d. Slide the free end of the flexible hose (mounted to the gun) onto the barbed gas fitting on the front of the Lincoln feeder. Move corresponding tubing clamp down near the end of the tube to assure a good gas seal.

Connection to Tweco Adapted Feeders and Lincoln DH-10, LN-10, PF-10 and STT-10 Feeders

Gun cable assemblies which were assembled with a **K613-2** Connection Kit will connect easily to any properly adapted feeder.

- a. Check that the adapter and feeder guide tubes, as well as the drive roll(s), are appropriate for the electrode size being used. For Lincoln feeders, check that the K1500-3 Gun Adapter is in place.
- b. Fully push the brass connector end of the gun cable into the brass adapter on the outgoing side of the feeder wire drive. Secure the cable using the hand screw or set screw in the adapter.
- c. Insert the control cable plug from the feeder trigger circuit into the mating socket on the gun cable connector handle.

Connection to Miller Feeders

Gun and cable assemblies which were assembled with a **K613-3** Connection Kit will connect easily to a variety of popular Miller wire feeders.

- a. Check that the gun liner, connector cap liner, drive roll(s) and guide tubes are appropriate for the electrode size being used.

- b. Fully push the brass connector end of the gun and cable into the connector receptacle on the outgoing side of the feeder wire drive. Tighten the hand screw to clamp down on the connector.
- c. Insert the control cable plug from the feeder trigger circuit into the mating socket on the gun cable connector handle.

Connection to Older Hobart Feeders

Gun and cable assemblies which were assembled with a **K613-4** Connection Kit will connect easily to a variety of older Hobart wire feeders.


- a. Check that the gun liner, connector cap liner, drive roll(s) and guide tubes are appropriate for the electrode size being used. Four different diameter pieces of liner material are included in each kit.
- b. Fully push the brass connector end of the gun and cable into the connector receptacle on the outgoing side of the feeder wire drive. Tighten the hand screw to clamp down on the connector.
- c. Insert the control cable plug from the feeder trigger circuit into the mating socket on the gun cable connector handle.
- d. Slide the free end of the flexible hose (mounted to the gun) onto the gas fitting on the Hobart wire feeder. Move the corresponding tubing clamp down near the end of the tube to assure a good gas seal.

Connection to Hobart Series 2000 Wire Feeders

Gun and cable assemblies which were assembled with a **K613-5** connection kit will connect to a variety of Hobart series 2000 wire feeders. If the wire feeder has not been revised to accept a 500 amp gun receptacle, install the gas inlet provided with the K613-5 kit as follows:

- a. Hold the gun receptacle and remove the gun receptacle knob. Lower the gun receptacle.
- b. Remove the two retaining screws that secure the gas inlet to the wire feeder and pull the gas inlet out. Then remove the gun sleeve. If the gun sleeve does not come out easily, insert a screwdriver into the slot provided and pry the sleeve out.
- c. Hold the gas tube with the hose attached and unscrew the gas inlet. Screw the gas inlet provided with the kit onto the gas tube.
- d. Slide the gas inlet into the wire feeder with the wide groove toward the drive rolls. Replace the retaining screws to secure the gas inlet in place.
- e. Raise the gun receptacle and reinstall the gun receptacle knob.
- f. Check that the gun liner, guide tubes and drive rolls are appropriate for the electrode size being used.
- g. Fully push the brass connector end of the gun and cable into the gas inlet and tighten the gun receptacle knob.

- h. Insert the control cable plug from the feeder trigger circuit into the mating socket on the gun cable connector.



Installation of Optional Gun Hanger (See Figure 2)

- a. Remove gun tube from gun by loosening the clamping screw with a 3/16" (4.8mm) Allen wrench.
- b. Slip hanger into collar so notches on hanger fit into slot on I.D. of collar. Slip the two parts onto the gun tube and hold in place by lightly tightening the set screw in the collar with a 5/64" (2.0mm) Allen wrench.
- c. Replace gun tube in gun and tighten socket head clamping screw. Position hanger on gun tube and tighten collar set screw.




Figure 2

OPERATION

Electrodes and Equipment

The MAGNUM® 550 guns and cables have been designed for use with Lincoln L-50 and L-56, solid steel wire electrodes for the GMAW process and Lincoln Outershield® cored electrodes for the gas-shielded flux-cored process. Refer to the appropriate Lincoln Process and Procedure Guidelines for the electrode used for information on recommended electrical and visible stickouts.

Making a Weld

WARNING

ELECTRIC SHOCK can kill.

- Do not touch electrically live parts or electrode with skin or wet clothing.
- Insulate yourself from work and ground.
- Always wear dry insulating gloves.

FUMES AND GASES can be dangerous.

- Keep your head out of fumes.
- Use ventilation or exhaust to remove fumes from breathing zone.

WELDING SPARKS can cause fire or explosion.

- Keep flammable material away.
- Do not weld on closed containers.

ARC RAYS can burn eyes and skin.

- Wear eye, ear and body protection.

See additional warning information at front of this operator's manual.

- a. Check that the welding power source is on and that the shielding gas supply is set for the proper flow rate.
- b. Position electrode over joint. End of the electrode should be slightly off the work.
- c. Lower welding helmet, close gun trigger, and begin welding. Hold the gun so the contact tip to work distance gives the correct electrical stickout as required for the procedure being used.
- d. To stop welding, release the gun trigger and then pull the gun away from the work after the arc goes out.
- e. If the optional interlocking trigger is installed, the trigger operates as follows:
 - Pull the trigger in to engage the feeder.
 - With the trigger pulled in all the way, the trigger can be slid forward into the interlock position.
 - To release interlock, squeeze trigger and pull back.

Avoiding Wire Feeding Problems

Wire feeding problems can be avoided by observing the following gun handling procedures:

- a. Do not kink or pull cable around sharp corners.
- b. Keep the electrode cable as straight as possible when welding or loading electrode through cable.
- c. Avoid wrapping excess cable around handle or front of wire feeder especially on 25 ft. (7.5m) length guns.
- d. Do not allow dolly wheels or trucks to run over cables.
- e. Keep cable clean by following maintenance instructions.
- f. Use only clean, rust-free electrode. The Lincoln electrodes have proper surface lubrication.
- g. Replace contact tip when the arc starts to become unstable or the contact tip end is fused or deformed.
- h. When using aluminum electrodes, 10 ft. maximum cable length is recommended. If longer cable lengths are used, cable should be kept as straight as possible.

MAINTENANCE

WARNING

ELECTRIC SHOCK can kill.

- **Have a qualified individual install and service this equipment.**

- **Turn the input power for the power source off at the fuse box or disconnect switch before working on this equipment.**

- **Do not touch electrically hot parts such as output terminals or internal wiring.**

Removal, Installation and Trimming Instructions for MAGNUM® Liners

NOTICE: The variation in cable lengths prevents the interchangeability of liners. Once a liner has been cut for a particular gun, it should not be installed in another gun, unless it can meet the liner cut off length requirement. Liners are shipped with the jacket of the liner extended the proper amount.

- Remove the gas nozzle and nozzle insulator. Loosen the set screw located in the side of the handle or in the diffuser with 5/64" (2.0mm) Allen wrench (provided with the gun or Connector Kit).
- Remove the gas diffuser from gun.
- Lay gun and cable out straight on a flat surface.

For K613-1 K613-2, K613-5 and K613-6 connections:

Loosen set screw located in the brass cable connector at the wire feeder end of the cable using the same 5/64" (2.0mm) Allen wrench. Pull liner out of cable. (Refer to Figure 1).

OR

For K613-3 and K613-4 connections:

Remove the connector cap. Remove gun tube and tap on end of liner to expose liner bushing on wire feeder end of cable. Pull liner out of cable. If the liner is going to be replaced with a different size liner, loosen set screw on the connector cap and remove piece of liner material.

- For installation and trimming instructions for MAGNUM® liners, see Liner Installation and Trimming Instructions.

Gun Tubes and Nozzles

- Replace worn contact tips as required.

- Remove spatter from inside of gas nozzle and from tip after each 10 minutes of arc time or as required.

- To remove gun tube from gun, loosen socket-head clamping screw in handle with 3/16" (4.8mm) Allen wrench. Remove coarse thread nozzle and coarse thread insulator assembly.

Pull gun tube out from gun handle. To reinstall, insert the gun tube, push in as far as possible, and retighten screw.

GUN CABLES

Cable Cleaning

Clean cable liner after using approximately 300 lbs (136 kg) of electrode. Remove the cable from the wire feeder and lay it out straight on the floor. Remove the contact tip from the gun. Using an air hose and only partial pressure, gently blow out the cable liner from the gas diffuser end.

CAUTION

Excessive pressure at the start may cause the dirt to form a plug.

Flex the cable over its entire length and again blow out the cable. Repeat this procedure until no further dirt comes out.

Cable Repair

The MAGNUM® 550 guns feature the use of repairable cable connectors. If the cable ever gets severely damaged, it may be cut shorter and repaired by the user. Repair cables as follows:

Gun Tube End Repair (Requires 2 No. S19492-2 Terminals)

- Remove the cable liner per Removal, Installation and Trimming Instructions.
- Remove the gun tube per section entitled "Gun Tubes and Nozzles".
- Remove four #6 screws from the gun handle, separate the two halves, and remove the cable from the handle along with the trigger assembly.
- Remove gun tube connector from cable by unscrewing connector nut from gun tube connector. If the cable inner tube is difficult to remove from the connector assembly, carefully slit it lengthwise with a knife up to the brass connector.

- e. Cut off the damaged section of cable and strip off the outer jacket as shown in Figure 3. Be careful not to cut the insulation on the control wires while stripping jacket. Strip the red and white control leads .25" (6.4mm) from the end and crimp a new S19492-2 terminal to each lead.

NOTE: The cable contains four control leads. Any two control leads can be used, provided the two colors used are the same at both ends. The extra leads are spares that can be used if one of the other leads breaks.

- f. Trim the inner tube to dimension shown.




Figure 3

- g. Slip the connector nut over the copper strands with the thread end out. Adjust gun tube connector so machined flat is on the same side of the cable as the red and white control leads. Assemble gun tube connector to cable by forcing the steel tube of the connector into the inside diameter of the cable inner tube until the copper strands are butted against the gun tube connector shoulder. Keeping the copper strands against the shoulder, pull the connector nut over the copper strands, engage the gun tube connector threads, and tighten in place. Refer to Figure 4.

NOTE: For best results, insert a .250" (6.4mm) diameter rod through the connector and into core of cable approximately 5.00" (127mm) when pushing the connector tube into the cable core tube. To tighten, hold the connector in place while turning the nut, then remove the rod from the core. This procedure assures the inner core does not kink while assembling or tightening.




Figure 4

- h. Pull the cut-off lead terminals off the trigger assembly and connect the replacement control lead terminals.
- i. Assemble cable in left side of gun handle. Assemble trigger into the proper handle cavity. Assemble right side of gun handle and tighten the four screws that hold the handle together. Refer to Figure 5. **NOTE: Be sure that protruded trigger ears are placed in cavities of both handles.**




Figure 5

- j. Install gun tube per section entitled “Gun Tube and Nozzles”.
- k. Install and trim liner per installation instructions.

Wire Feeder End Repair (Requires 2 No. S19492-1 Terminals)

- a. Remove the cable liner per the Maintenance Section.
- b. Remove the feeder end connector, molded gas plug (or barbed fitting), cable handle nut, plastic tailpiece, and connector cover (See Figure 6).
NOTE: In order to remove the cable handle nut, the tail of the connector cover must be depressed and the cable handle nut rotated 1/4 turn counter-clockwise as viewed from the feeder end.
- c. Remove incoming connector from cable by unscrewing connector nut from incoming connector. If the cable inner tube is difficult to remove from the connector assembly, carefully slit it lengthwise with a knife up to the brass connector.
- d. Move the cable boot, cable handle, and strain relief toward the middle of the cable past the damaged section.
- e. Cut off the damaged section of cable and strip off the outer jacket as shown in Figure 3. Be careful not to cut the insulation on the control wires while stripping jacket. Strip the red and white control leads 1/4” (6.4mm) from the end and crimp a new S19492-1 terminal to each lead. Trim the inner tube to dimensions shown.
NOTE: The cable contains four control leads. Any two control leads can be used, provided the two colors used are the same at both ends. The extra leads are spares that can be used if one of the other leads breaks.

- f. Check that the cable boot, cable handle and strain relief are on the cable. Slip the connector nut over the copper strands with the threaded end out. Assemble incoming connector to cable by forcing the steel tube of the connector into the inside diameter of the cable inner tube until the copper strands are butted against the incoming connector shoulder. Keeping the copper strands against the shoulder, pull the connector nut over the copper strands, engage the incoming connector threads, and tighten in place. Refer to Figure 4.

NOTE: For best results, insert a .250” (6.4mm) diameter rod through the connector and into core of cable approximately 11.00” (280mm) when pushing the connector tube into the cable core tube. To tighten, hold the connector in place while turning the nut, then remove the rod from the core. This procedure assures the inner core does not kink while assembling or tightening.

Position the plastic strain relief such that the tapered end is 7.10” (180mm) from the incoming connector (See Figure 6). Lock into place with steel housing.

- g. Position cable boot and cable handle on cable and assemble replacement control wire terminals in place on the cable handle. Insert connector cover in place. Install tailpiece and fasten to cable handle with cable handle nut. Refer to Figure 6.
- h. Replace the molded gas plug (or barbed fitting) and feeder end connector.
- i. Install and trim liner per installation instructions.






Figure 6



HOW TO USE TROUBLESHOOTING GUIDE

WARNING

Service and Repair should only be performed by Lincoln Electric Factory Trained Personnel. Unauthorized repairs performed on this equipment may result in danger to the technician and machine operator and will invalidate your factory warranty. For your safety and to avoid Electrical Shock, please observe all safety notes and precautions detailed throughout this manual.

This Troubleshooting Guide is provided to help you locate and repair possible machine malfunctions. Simply follow the three-step procedure listed below.

Step 1. LOCATE PROBLEM (SYMPTOM).

Look under the column labeled "PROBLEM (SYMPTOMS)". This column describes possible symptoms that the machine may exhibit. Find the listing that best describes the symptom that the machine is exhibiting.

Step 2. POSSIBLE CAUSE.

The second column labeled "POSSIBLE CAUSE" lists the obvious external possibilities that may contribute to the machine symptom.

Step 3. RECOMMENDED COURSE OF ACTION

This column provides a course of action for the Possible Cause.

If you do not understand or are unable to perform the Recommended Course of Action safely, contact your local Lincoln Authorized Field Service Facility.

WARNING

ELECTRIC SHOCK can kill.

- Have a qualified individual install and service this equipment.
- Turn the input power off at the fuse box before working on equipment.
- Do not touch electrically hot parts.

CAUTION

If for any reason you do not understand the test procedures or are unable to perform the tests/repairs safely, contact your **Local Lincoln Authorized Field Service Facility** for technical troubleshooting assistance before you proceed.

Observe all Safety Guidelines detailed throughout this manual

PROBLEMS (SYMPTOMS)	POSSIBLE CAUSE	RECOMMENDED COURSE OF ACTION
Drive rolls turn, but wire will not feed or wire feeding is rough.	<ul style="list-style-type: none"> a. Gun cable kinked and/or twisted. b. Wire jammed in gun and cable. c. Incorrect drive rolls and guide tubes. d. Gun cable liner dirty. e. Worn drive rolls. f. Electrode rusty and/or dirty. g. Worn or improper size cable liner. h. Partially flashed, melted, or improper size contact tip. i. Incorrect diffuser. 	<ul style="list-style-type: none"> a. Keep as straight as possible. Inspect cable and replace if necessary. b. Remove wire from gun and cable - feed in new wire. Note any obstruction. Replace liner if necessary. c. Be sure the wire diameter being used is stamped on drive rolls and guide tubes. Replace if necessary. d. Clean liner or replace. e. Replace or reverse split drive roll type. f. Replace the electrode if it is rusty. g. Replace cable liner. h. Replace the contact tip. i. Be sure diffuser size is correct for the electrode being used.
Variable or "hunting" arc.	<ul style="list-style-type: none"> a. Contact tip worn or incorrect size. b. Worn or undersize ground cables or poor ground connections. c. Loose electrode connections. 	<ul style="list-style-type: none"> a. Replace contact tip. b. Inspect - repair or replace as necessary. c. Be sure the following connections are tight: electrode cable to wire feeder and power source, work cable to power source and work, gun cable to wire feeder contact block, gun nozzle to body, and contact tip to nozzle.
Poor arc striking with sticking or "Blast-offs", weld porosity, narrow and ropy looking bead, or electrode stubbing into plate while welding.	<ul style="list-style-type: none"> a. Improper procedures or techniques. b. Improper gas shielding. 	<ul style="list-style-type: none"> a. See "Gas Metal Arc Welding" (GS-100). b. Clean gas nozzle, Make certain that gas diffuser is not restricted. Make certain that gas cylinder is not empty or turned off. Make certain gas solenoid valve is operating and gas flow rate is proper. Remove gun liner and check rubber seal for any sign of deterioration or damage. Be sure set screw in brass connector is in place and tightened against the liner bushing.
Tip seizes in diffuser.	<ul style="list-style-type: none"> a. Tip overheating due to prolonged or excessive high current and/or duty cycle welding. 	<ul style="list-style-type: none"> a. Do not exceed current and duty cycle rating of gun. A light application of high temperature antiseize lubricant (such as Lincoln E2067 Graphite Grease) may be applied to tip threads.

CAUTION

If for any reason you do not understand the test procedures or are unable to perform the tests/repairs safely, contact your **Local Lincoln Authorized Field Service Facility** for technical troubleshooting assistance before you proceed.

MAGNUM® 550



NOTES



NOTES



			
WARNING	<ul style="list-style-type: none"> ● Do not touch electrically live parts or electrode with skin or wet clothing. ● Insulate yourself from work and ground. 	<ul style="list-style-type: none"> ● Keep flammable materials away. 	<ul style="list-style-type: none"> ● Wear eye, ear and body protection.
Spanish AVISO DE PRECAUCION	<ul style="list-style-type: none"> ● No toque las partes o los electrodos bajo carga con la piel o ropa mojada. ● Aíselese del trabajo y de la tierra. 	<ul style="list-style-type: none"> ● Mantenga el material combustible fuera del área de trabajo. 	<ul style="list-style-type: none"> ● Protéjase los ojos, los oídos y el cuerpo.
French ATTENTION	<ul style="list-style-type: none"> ● Ne laissez ni la peau ni des vêtements mouillés entrer en contact avec des pièces sous tension. ● Isolez-vous du travail et de la terre. 	<ul style="list-style-type: none"> ● Gardez à l'écart de tout matériel inflammable. 	<ul style="list-style-type: none"> ● Protégez vos yeux, vos oreilles et votre corps.
German WARNUNG	<ul style="list-style-type: none"> ● Berühren Sie keine stromführenden Teile oder Elektroden mit Ihrem Körper oder feuchter Kleidung! ● Isolieren Sie sich von den Elektroden und dem Erdboden! 	<ul style="list-style-type: none"> ● Entfernen Sie brennbares Material! 	<ul style="list-style-type: none"> ● Tragen Sie Augen-, Ohren- und Körperschutz!
Portuguese ATENÇÃO	<ul style="list-style-type: none"> ● Não toque partes elétricas e electrodos com a pele ou roupa molhada. ● Isole-se da peça e terra. 	<ul style="list-style-type: none"> ● Mantenha inflamáveis bem guardados. 	<ul style="list-style-type: none"> ● Use proteção para a vista, ouvido e corpo.
Japanese 注意事項	<ul style="list-style-type: none"> ● 通電中の電気部品、又は溶材にヒフやぬれた布で触れないこと。 ● 施工物やアースから身体が絶縁されている様にして下さい。 	<ul style="list-style-type: none"> ● 燃えやすいものの側での溶接作業は絶対にしてはなりません。 	<ul style="list-style-type: none"> ● 目、耳及び身体に保護具をして下さい。
Chinese 警告	<ul style="list-style-type: none"> ● 皮肤或湿衣物切勿接触带电部件及焊条。 ● 使你自已与地面和工件绝缘。 	<ul style="list-style-type: none"> ● 把一切易燃物品移离工作场所。 	<ul style="list-style-type: none"> ● 佩戴眼、耳及身体劳动保护用具。
Korean 위험	<ul style="list-style-type: none"> ● 전도체나 용접봉을 젖은 헝겍 또는 피부로 절대 접촉치 마십시오. ● 모재와 접지를 접촉치 마십시오. 	<ul style="list-style-type: none"> ● 인화성 물질을 접근 시키지 마십시오. 	<ul style="list-style-type: none"> ● 눈, 귀와 몸에 보호장구를 착용하십시오.
Arabic تحذير	<ul style="list-style-type: none"> ● لا تلمس الاجزاء التي يسري فيها التيار الكهربائي أو الألكترود بجلد الجسم أو بالملابس المبللة بالماء. ● ضع عازلا على جسمك خلال العمل. 	<ul style="list-style-type: none"> ● ضع المواد القابلة للاشتعال في مكان بعيد. 	<ul style="list-style-type: none"> ● ضع أدوات وملابس واقية على عينيك وأذنيك وجسمك.

READ AND UNDERSTAND THE MANUFACTURER'S INSTRUCTION FOR THIS EQUIPMENT AND THE CONSUMABLES TO BE USED AND FOLLOW YOUR EMPLOYER'S SAFETY PRACTICES.

SE RECOMIENDA LEER Y ENTENDER LAS INSTRUCCIONES DEL FABRICANTE PARA EL USO DE ESTE EQUIPO Y LOS CONSUMIBLES QUE VA A UTILIZAR, SIGA LAS MEDIDAS DE SEGURIDAD DE SU SUPERVISOR.

LISEZ ET COMPRENEZ LES INSTRUCTIONS DU FABRICANT EN CE QUI REGARDE CET EQUIPMENT ET LES PRODUITS A ETRE EMPLOYES ET SUIVEZ LES PROCEDURES DE SECURITE DE VOTRE EMPLOYEUR.

LESEN SIE UND BEFOLGEN SIE DIE BETRIEBSANLEITUNG DER ANLAGE UND DEN ELEKTRODENEINSATZ DES HERSTELLERS. DIE UNFALLVERHÜTUNGSVORSCHRIFTEN DES ARBEITGEBERS SIND EBENFALLS ZU BEACHTEN.

			
<ul style="list-style-type: none"> ● Keep your head out of fumes. ● Use ventilation or exhaust to remove fumes from breathing zone. 	<ul style="list-style-type: none"> ● Turn power off before servicing. 	<ul style="list-style-type: none"> ● Do not operate with panel open or guards off. 	WARNING
<ul style="list-style-type: none"> ● Los humos fuera de la zona de respiración. ● Mantenga la cabeza fuera de los humos. Utilice ventilación o aspiración para gases. 	<ul style="list-style-type: none"> ● Desconectar el cable de alimentación de poder de la máquina antes de iniciar cualquier servicio. 	<ul style="list-style-type: none"> ● No operar con panel abierto o guardas quitadas. 	Spanish AVISO DE PRECAUCION
<ul style="list-style-type: none"> ● Gardez la tête à l'écart des fumées. ● Utilisez un ventilateur ou un aspirateur pour ôter les fumées des zones de travail. 	<ul style="list-style-type: none"> ● Débranchez le courant avant l'entretien. 	<ul style="list-style-type: none"> ● N'opérez pas avec les panneaux ouverts ou avec les dispositifs de protection enlevés. 	French ATTENTION
<ul style="list-style-type: none"> ● Vermeiden Sie das Einatmen von Schweißrauch! ● Sorgen Sie für gute Be- und Entlüftung des Arbeitsplatzes! 	<ul style="list-style-type: none"> ● Strom vor Wartungsarbeiten abschalten! (Netzstrom völlig öffnen; Maschine anhalten!) 	<ul style="list-style-type: none"> ● Anlage nie ohne Schutzgehäuse oder Innenschutzverkleidung in Betrieb setzen! 	German WARNUNG
<ul style="list-style-type: none"> ● Mantenha seu rosto da fumaça. ● Use ventilação e exaustão para remover fumo da zona respiratória. 	<ul style="list-style-type: none"> ● Não opere com as tampas removidas. ● Desligue a corrente antes de fazer serviço. 	<ul style="list-style-type: none"> ● Mantenha-se afastado das partes moventes. ● Não opere com os painéis abertos ou guardas removidas. 	Portuguese ATENÇÃO
<ul style="list-style-type: none"> ● ヒュームから頭を離すようにして下さい。 ● 換気や排煙に十分留意して下さい。 	<ul style="list-style-type: none"> ● メンテナンス・サービスに取りかかる際には、まず電源スイッチを必ず切って下さい。 	<ul style="list-style-type: none"> ● パネルやカバーを取り外したままで機械操作をしないで下さい。 	Japanese 注意事項
<ul style="list-style-type: none"> ● 頭部遠離煙霧。 ● 在呼吸區使用通風或排風器除煙。 	<ul style="list-style-type: none"> ● 維修前切斷電源。 	<ul style="list-style-type: none"> ● 儀表板打開或沒有安全罩時不準作業。 	Chinese 警告
<ul style="list-style-type: none"> ● 얼굴로부터 용접가스를 멀리하십시오. ● 호흡지역으로부터 용접가스를 제거하기 위해 가스제거기나 통풍기를 사용하십시오. 	<ul style="list-style-type: none"> ● 보수전에 전원을 차단하십시오. 	<ul style="list-style-type: none"> ● 판넬이 열린 상태로 작동치 마십시오. 	Korean 위험
<ul style="list-style-type: none"> ● ابعد رأسك بعيداً عن الدخان. ● استعمل التهوية أو جهاز ضغط الدخان للخارج لكي تبعد الدخان عن المنطقة التي تتنفس فيها. 	<ul style="list-style-type: none"> ● اقطع التيار الكهربائي قبل القيام بأية صيانة. 	<ul style="list-style-type: none"> ● لا تشغيل هذا الجهاز اذا كانت الاغطية الحديدية الواقية ليست عليه. 	Arabic تحذير

LEIA E COMPREENDA AS INSTRUÇÕES DO FABRICANTE PARA ESTE EQUIPAMENTO E AS PARTES DE USO, E SIGA AS PRÁTICAS DE SEGURANÇA DO EMPREGADOR.

使う機械や溶材のメーカーの指示書をよく読み、まず理解して下さい。そして貴社の安全規定に従って下さい。

請詳細閱讀並理解製造廠提供的說明以及應該使用的銀焊材料，並請遵守貴方的有關勞動保護規定。

이 제품에 동봉된 작업지침서를 숙지하시고 귀사의 작업자 안전수칙을 준수하시기 바랍니다.

اقرأ بتمعن وافهم تعليمات المصنع المنتج لهذه المعدات والمواد قبل استعمالها واتبع تعليمات الوقاية لصاحب العمل.

CUSTOMER ASSISTANCE POLICY

The business of The Lincoln Electric Company is manufacturing and selling high quality welding equipment, consumables, and cutting equipment. Our challenge is to meet the needs of our customers and to exceed their expectations. On occasion, purchasers may ask Lincoln Electric for advice or information about their use of our products. We respond to our customers based on the best information in our possession at that time. Lincoln Electric is not in a position to warrant or guarantee such advice, and assumes no liability, with respect to such information or advice. We expressly disclaim any warranty of any kind, including any warranty of fitness for any customer's particular purpose, with respect to such information or advice. As a matter of practical consideration, we also cannot assume any responsibility for updating or correcting any such information or advice once it has been given, nor does the provision of information or advice create, expand or alter any warranty with respect to the sale of our products.

Lincoln Electric is a responsive manufacturer, but the selection and use of specific products sold by Lincoln Electric is solely within the control of, and remains the sole responsibility of the customer. Many variables beyond the control of Lincoln Electric affect the results obtained in applying these types of fabrication methods and service requirements.

Subject to Change – This information is accurate to the best of our knowledge at the time of printing. Please refer to www.lincolnelectric.com for any updated information.



THE LINCOLN ELECTRIC COMPANY

22801 St. Clair Avenue • Cleveland, OH • 44117-1199 • U.S.A.
Phone: +1.216.481.8100 • www.lincolnelectric.com