

Pulse-On-Pulse™ GMAW Weld Process Guide

Overview

Pulse on Pulse GMAW® – GTAW appearance with GMAW productivity.

- **Excellent control of heat input on thinner materials.**
- **Eliminates in-line weaving.**
- **Optimum productivity in robotic and semi-automatic applications.**
- **Uniform, consistent beads on welds in which appearance is critical.**
- **Easier training/Skill level.**

Index


Details _____	1
Process Description	
Waveform	
Optimization _____	2
Utilizing Pulse-On-Pulse™	
When to use Pulse-On-Pulse™	
Applications _____	3-4
1F, 2F and 3F Lap & Fillet	
1G Butt & Groove	
Set-up _____	5-7
Connection Diagram	
Troubleshooting	
Glossary _____	8
Icons	
Technical Terms	
Procedure Notes	
Customer Assistance Policy	




Process Description

Pulse on Pulse™ (GMAW-PP) is a Lincoln patented process specifically designed for use in welding relatively thin (less than 1/4" thick) aluminum. It produces weld beads with very consistent uniform ripple.


In Pulse on Pulse modes, two distinct pulse types are used, instead of the single pulse type normally used in GMAW-P. A number of high energy pulses are used to obtain spray transfer and transfer metal across the arc. After a number of such pulses, depending on the wire feed speed used, an identical number of low energy pulses are performed. The Peak Current, Background Current, and Frequency are identical for the high energy and low energy pulses. However, the details of the current ramp up and ramp down rates mean that a low energy pulse contains less energy than a high energy pulse. In addition to cooling the weld down, the major effect of the low energy pulses is that they form a weld ripple. Since they occur at very regular time intervals, the weld bead obtained is very uniform with a very consistent ripple pattern. In fact, the bead has its best appearance if no oscillation of the welding gun ("whipping") is used.



Waveform




Utilizing Pulse-On-Pulse™




Adjust WFS to:

- Control the weld deposition rate.
- Control heat input.



Adjust TRIM to:

- Control the arc length for a more stable process.



Adjust UltimArc™ to:

- Increase or decrease the space between the “ripples.”




+10

0

-10




1F / PA Lap & Fillet



- Use a 10-20° push angle.
- Use a 35° work angle.
- Position the electrode approximately one electrode diameter outside the joint favoring the bottom leg.
- For 14 ga applications position the electrode directly in the joint or slightly favoring the top edge. May require decreased work angle.

2F / PB Lap & Fillet



- Use a 10-20° push angle.
- Use a 40° work angle.
- Position the electrode approximately one electrode diameter outside the joint favoring the bottom leg.

100% Ar 4043 Alloy 0.035" dia.		
	in	in/min
4043 Alloy 3/64" dia.	1/4 in	600.0
	3/16 in	550.0
	10 ga	400.0
	12 ga	300.0
	14 ga	220.0
16 ga	150.0	

4043 Alloy 3/64" dia.	1/4 in	400.0
	3/16 in	340.0
	10 ga	300.0
	12 ga	250.0
	14 ga	135.0
16 ga	100.0	

100% Ar 5356 Alloy 0.035" dia.		
	in	in/min
5356 Alloy 3/64" dia.	1/4 in	700.0
	3/16 in	670.0
	10 ga	550.0
	12 ga	400.0
	14 ga	300.0
16 ga	225.0	

5356 Alloy 3/64" dia.	1/4 in	500.0
	3/16 in	375.0
	10 ga	300.0
	12 ga	200.0
	14 ga	175.0
16 ga	125.0	

100% Ar 4043 Alloy 0.035" dia.		
	in	in/min
4043 Alloy 3/64" dia.	1/4 in	600.0
	3/16 in	550.0
	10 ga	400.0
	12 ga	300.0
	14 ga	220.0
16 ga	150.0	

4043 Alloy 3/64" dia.	1/4 in	400.0
	3/16 in	340.0
	10 ga	300.0
	12 ga	250.0
	14 ga	135.0
16 ga	100.0	


100% Ar 5356 Alloy 0.035" dia.		
	in	in/min
5356 Alloy 3/64" dia.	1/4 in	700.0
	3/16 in	670.0
	10 ga	550.0
	12 ga	400.0
	14 ga	300.0
16 ga	225.0	

5356 Alloy 3/64" dia.	1/4 in	500.0
	3/16 in	375.0
	10 ga	300.0
	12 ga	200.0
	14 ga	175.0
16 ga	125.0	

Trim and Ultimarc should be used at the nominal settings. Adjust to application settings.


See Customer Assistance Policy and Disclaimer Notice on page 8.

3F / PG Lap & Fillet



- Use a 10° drag angle.
- Use a 30° work angle.
- Position the electrode approximately one electrode diameter outside the joint favoring the bottom leg.
- For 14 ga applications position the electrode directly in the joint or slightly favoring the edge.

1G / 2G Butt & Groove



- Use a 10° drag angle.
- Use a 30° work angle.
- Position the electrode approximately one electrode diameter outside the joint favoring the bottom leg.
- For 14 ga applications position the electrode directly in the joint or slightly favoring the edge.

100% Ar	↕	o/o		
4043 Alloy 0.035" dia.	↕	o/o	in/min	
			1/4 in	600.0
			3/16 in	550.0
			10 ga	400.0
			12 ga	300.0
			14 ga	220.0
16 ga	150.0			

4043 Alloy 3/64" dia.	1/4 in	400.0
	3/16 in	340.0
	10 ga	300.0
	12 ga	250.0
	14 ga	135.0
16 ga	100.0	

100% Ar	↕	o/o		
5356 Alloy 0.035" dia.	↕	o/o	in/min	
			1/4 in	700.0
			3/16 in	670.0
			10 ga	550.0
			12 ga	400.0
			14 ga	300.0
16 ga	225.0			

5356 Alloy 3/64" dia.	1/4 in	500.0
	3/16 in	375.0
	10 ga	300.0
	12 ga	200.0
	14 ga	175.0
16 ga	125.0	

100% Ar	↕	o/o		
4043 Alloy 0.035" dia.	↕	o/o	in/min	
			1/4 in	600.0
			3/16 in	550.0
			10 ga	400.0
			12 ga	300.0
			14 ga	220.0
16 ga	150.0			

4043 Alloy 3/64" dia.	1/4 in	400.0
	3/16 in	340.0
	10 ga	300.0
	12 ga	250.0
	14 ga	135.0
16 ga	100.0	


100% Ar	↕	o/o		
5356 Alloy 0.035" dia.	↕	o/o	in/min	
			1/4 in	700.0
			3/16 in	670.0
			10 ga	550.0
			12 ga	400.0
			14 ga	300.0
16 ga	225.0			

5356 Alloy 3/64" dia.	1/4 in	500.0
	3/16 in	375.0
	10 ga	300.0
	12 ga	200.0
	14 ga	175.0
16 ga	125.0	

Trim and Ultimarc should be used at the nominal settings. Adjust to application settings.

See Customer Assistance Policy and Disclaimer Notice on page 8.

Connection Diagram



Troubleshooting

Check ▶	Volts	Contact Tip to Work Distance	Wire Feed Speed	Gas Coverage	Surface Contaminants	Push Angle
Spatter						
Action ▶						


Check ▶	Proper Feeding	Tip	Volts	Surface Contaminants
Erratic Arc				
Action ▶				


Check ▶	Gas Coverage	Surface Contaminants	Contact Tip to Work Distance
Porosity			
Action ▶			

Check ▶	Gas Coverage	Contact Tip to Work Distance	Push Angle	Arc Control
Smut / Soot				
Action ▶				


Increase
 Decrease
 Inspect & Replace
 Important


Troubleshooting

Check ▶	 Volts	 Wire Feed Speed	 Push Angle
 Concave Bead			
Action ▶			

Check ▶	 Volts	 Travel Speed	 Wire Feed Speed	 Push Angle
 Under Cut				
Action ▶				


Check ▶	 Travel Speed	 Wire Feed Speed
 Burn Through		
Action ▶		

Check ▶	 Travel Speed	 Wire Feed Speed	 Volts	 Push Angle
 Convex Bead				
Action ▶				

Check ▶	 Travel Speed	 Wire Feed Speed	 Volts
 Poor Penetration			
Action ▶			

	Increase		Decrease		Inspect & Replace		Important
---	----------	---	----------	---	-------------------	---	-----------

Icons

 Wire Type	 Gas	 Material Thickness	 Wire Feed Speed	 Travel Speed	 Volts	 Trim	 Control Knob	 High Heat	 Low Heat
 Torch Nozzle	 Travel Speed (Slow)	 Travel Speed (Fast)	 Spatter (Minimal)	 Spatter	 Arc Length	 Wire Diameter	 Push Angle	 Gas Coverage	 Surface Contaminants
 Contact Tip to Work Distance	 Porosity	 Concave Bead	 Under Cut	 Burn Through	 Convex Bead	 Poor Penetration	 Smut / Soot		

Technical Terms

GMAW _____ Gas metal arc welding including metal inert gas (MIG) and metal active gas (MAG) welding.

Porosity _____ Gas entrapped in solidifying metal forms spherical or elongated pores in the weld.

Push Angle _____ The angle at which the electrode leads the weld pool relative to the direction of travel.

Synergic _____ A mode of control which automatically selects a preprogrammed nominal voltage based on the wire feed speed (WFS) set by the operator.

Work Angle _____ The angle of the electrode, off perpendicular, relative to the work piece surface.

Procedure Notes

All listed procedures are starting points and may require some adjustment depending on the specific application.

Torch angle, electrode placement, contamination, mill scale, joint fit up, and joint consistency are factors that may require special consideration depending on the specific application.

At higher travel speeds, joint fit up, wire placement, and contamination all become factors that are more significant.

The result of welding at higher travel speeds is a tendency to produce more spatter, less penetration, more undercut, and a less desirable bead shape. Depending on the limitations / requirements of the actual application, slower travel speeds and higher arc voltages may be required.

As the travel speed increases in fast follow applications (1/4" to 14 Gauge), a tighter and arc length must be maintained so that the puddle properly follows the arc. Operators typically reduce the arc length control (Trim) to achieve this.

At faster travel speeds, the bead-shape can become very convex (or ropy), and the weld will not "wet" well. There is a point at which the arc is set so short that the arc will become unstable and stubbing will occur. This forms a limitation of just how fast the travel speed can be raised.

It is ultimately the responsibility of the end user to ensure the proper weld deposition rate, bead profile, and structural integrity of a given weld application.

Customer Assistance Policy

The business of The Lincoln Electric Company is manufacturing and selling high quality welding equipment, consumables, and cutting equipment. Our challenge is to meet the needs of our customer and to exceed their expectations. On occasion, purchasers may ask Lincoln Electric for advice or information about their use of our products. We respond to our customers based on the best information in our possession at that time. Lincoln Electric is not in a position to warrant or guarantee such advice, and assumes no liability, with respect to such information or advice. We expressly disclaim any warranty of any kind, including any warranty of fitness for any customer's particular purpose, with respect to such information or advice. As a matter of practical consideration, we also cannot assume any responsibility for updating or correcting any such information or advice once it has been given, nor does the provision of information or advice create, expand or alter any warranty with respect to the sale of our products.

Lincoln Electric is a responsive manufacturer, but the selection and use of specific products sold by Lincoln Electric is solely within the control of, and remains the sole responsibility of the customer. Many variables beyond the control of Lincoln Electric affect the results obtained in applying these types of fabrication methods and service requirement. Subject to change.

This information is accurate to the best of our knowledge at the time of printing. Please refer to www.lincolnelectric.com for any updated information.