

TECHNICAL INFORMATION SHEET

HARRIS ER80S-D2 WELDING FILLER METAL

APPLICATION:

80S-D2 contains molybdenum and manganese for increased strength. Silicon as a de-oxidizer to control porosity when welding with CO₂. The weld deposit yields excellent quality the bead appearance on carbon and low-alloy steel provides an excellent quality weld.

NOMINAL CHEMICAL COMPOSITION:

.025% max	Carbon	.0712%
.50% max	Manganese	1.60-2.10%
.50 % max	Sulfur	.025% max
.15% max	Silicon	.5080%
Balance	Molybdenum	.4060%
	.025% max .50% max .50 % max .15% max Balance	.50% maxManganese.50 % maxSulfur.15% maxSilicon

TYPICAL MECHANICAL PROPERTIES AS WELDED:

(Properties are greatly influenced by the preheat, inter-pass and post-heat used)Tensile Strength (psi)84,000Elongation % in 2"19%Impact Requirements20 ft.lbf at -20°F

* RECOMMENDED WELDING PARAMETERS:

GMAW (MIG) Parameters (DC Reverse Polarity) Electrode Positive Spray transfer

Wire Diameter	AMPS	VOLTS	(3) CO2/ AR-CO2 (cfh)	Wire Feed imp		
.023	100-160	22-26	25	410-720		
.030	135-230	24-28	25	390-670		
.035	165-300	24-28	30	360-520		
.045	200-375	24-30	30-35	210-390		
⁽³⁾ Setting based on CO ₂ for mild steel, Ar-CO ₂ for low alloy steel						

All statements, information and data given are believed to be accurate and reliable but are presented without guarantee, warranty or responsibility of any kind, expressed or implied.



<u>Material</u>	<u>Tungsten dia.</u> (1)	Filler Wire Size	<u>Amps</u>	<u>Gas Cup</u>	<u>Argon (cfh)</u>
1/16"	1/16"	1/16"	100-140	3/8	20
3/32"	1/16"	1/16"	100-160	3/8	20
1/8"	3/32"	1/16"	125-200	7/16	20
3/16"	3/32"	3/32"	150-250	7/16	25
1/4"	1/8"	1/8"	150-250	1/2	25
3/8"	1/8"	1/8"	150-275	1/2	25
1/2"	1/8"	1/8"	150-300	1/2	25

GTAW (TIG) Parameters (DCSP) 2 % Thoriated Tungsten Electrode negative ⁽¹⁾

* All parameters are suggested as basic guidelines and will vary depending on joint design number of passes, and other factors.

SPECIFICATION COMPLIANCE: AISI/AWS A5.28 & ASME SFA 5.28 ER 80S-D2

WARNING: PROTECT yourself and others. Read and understand this information.

FUMES AND GASES can be hazardous to your health.

HEAT RAYS, (infrared radiation) from flame or hot metal can injure eyes.

- Before use, read and understand the manufacturer's instructions, Safety Data Sheets (SDS), and your employer's safety practices.
- Keep your head out of fumes.
- Use enough ventilation, exhaust at the flame, or heat source, to keep fumes and gases from your breathing zone and the general area.
- Wear correct eye, ear, and body protection.
- See American National Standard Z49.1, Safety in Welding, Cutting, and Allied Processes, published by the American Welding Society, 8669 Doral Blvd., Doral, Florida 33166; OSHA Safety and Health Standards, available from the U.S. Government Office, Washington, DC 20402.

STATEMENT OF LIABILITY- DISCLAIMER

Any suggestion of product applications or results is given without representation or warranty, either expressed or implied. Without exception or limitation, there are no warranties of merchantability or of fitness for particular purpose or application. The user must fully evaluate every process and application in all aspects, including suitability, compliance with applicable law and non-infringement of the rights of others. The Harris Products Group and its affiliates shall have no liability in respect thereof.

All statements, information and data given are believed to be accurate and reliable but are presented without guarantee, warranty or responsibility of any kind, expressed or implied.