

MARQUETTE®

**Model 10 - 119
235 Amp
Welder**

**Operating Instructions
Parts List**



APPLIED POWER
INC.

Your new A.C. Arc Welder is a fine piece of equipment, carefully engineered, constructed of the finest materials and thoroughly tested before being delivered to you. It will provide the ultimate in performance, convenience and reliability.

In order that you may utilize to the fullest extent the capabilities of superior performance that your welder will provide, we ask that you please:

CAREFULLY READ AND FOLLOW THE INSTRUCTIONS OUTLINED IN THIS PAMPHLET

Please fill in the following information so that you will have a complete record of your welder. If you have any occasion to correspond with the dealer or the factory about this welder, please be sure to give all the information that you have filled in.

MODEL	SERIAL NUMBER	DATE OF PURCHASE

WARRANTY, PRODUCT SERVICE AND PARTS

The manufacturer warrants this equipment to the original user against defective material and workmanship for a period of one year from date of purchase.

The manufacturer's responsibility under this warranty is limited to the repair or replacement of the defective part or parts. During the warranty period, all parts and repair labor are covered for one year from the date of purchase.

The manufacturer reserves the right to determine whether the part or parts failed because of defective material, workmanship, or other causes. Failure caused by accident, alteration, misuse, or improper packaging of returned units is not covered by this warranty.

All equipment sent in for repair must be shipped transportation prepaid, and the repaired unit will be returned transportation prepaid.

The rights under this warranty are limited to the original user and may not be transferred to subsequent owners.

This warranty is in lieu of all other warranties expressed or implied, including any implied warranty or merchantability or fitness for a particular purpose. In no event will the manufacturer be liable for consequential or indirect damages.

Service parts, warranty, and regular repair service for products are available through a nationwide system of company owned Factory Service Centers and independently owned Authorized Service Centers which are carefully selected by the Automotive Product Service Division. Your distributor or jobber can provide you with a list of Service Centers in your area.

Should additional assistance be required, please contact:

Automotive Product Service Division
Automotive Service Systems Group
P.O. Box 7580
Milwaukee, Wisconsin 53222
Telephone: 414/257-2800

DESCRIPTION

A.C. POWER CORD

The a.c. power cord is a 3-conductor cable with 3-prong polarized plug. Two conductors carry power, the third grounds the Welder case for safety. A matching receptacle, 638-69460, is available for connection to the power lines.

WORK AND ELECTRODE CABLES

The work cable is a heavy-duty flexible type supplied with a work clamp for one end and a plug at the other end. The clamp connects to the work to provide a return path for the welding current.

The electrode cable is a heavy-duty flexible type supplied with an insulated, self-adjusting holder that can grip 1/16" to 7/32" electrodes and hold them at various angles.

The work and electrode cables plug into jacks on the Welder panel to provide up to 21 different heats.

One cable is plugged into the numbered jack covering the current group desired. The other cable is plugged into the HI, MED or LO jack to give the desired current within this group. The Welder nameplate shows recommended current taps to use for various electrode sizes.

HELMET

The helmet protects against flash and welding spatter. The polished No. 10 filter lens is protected by a cover glass, both of which are replaceable.

ELECTRICAL SPECIFICATIONS FOR MODEL 10-119 WELDER										
Primary							Secondary			
Volts*	Amps* (Rated)	Cycles*	Phase	KW	KVA	Power Factor	Open Circuit Volts	Arc Volts	Arc Amps	Duty Cycle
208/230	50/45	60	Single	9.12	12.58	75%	80 (max.)	25	40-235	20%

* See welder rating plate.

INSTALLATION

LOCATION

Choose a location for the Welder that is dry, well lighted and convenient to the work area. Ventilation around the machine is important since cooling of the unit depends on free circulation of air through the cabinet. Do not cover the ventilating holes.

To minimize arc weld flashing, use a canvas curtain around the immediate welding area. The curtain will also stop flying sparks. Be sure the work area is free of combustible materials.

ELECTRICAL CONNECTIONS

Before making electrical connections, consult a competent electrician for any new wiring required to meet local electric code specifications. This welder operates on single phase current having two supply wires and a ground wire. See illustration for connections from power lines to receptacle.

CAUTION: This Welder operates on alternating current only. Connection to a power source of direct current, or other than specified on the nameplate, can result in serious damage to the transformer windings.

INSTALLATION (cont.)

FUSE REQUIREMENTS

This Welder draws an intermittent load from the power supply and is fused to permit these momentary heavy currents. Recommended fuse sizes are listed in the Fuse Chart below. See Welder nameplate for rated line voltage.

FUSE CHART	
Line Voltage	Fuse Size
208 V	90 Amp
220-230 V	80 Amp
440-460 V	40 Amp


CONNECTIONS TO POWER LINE

Connect single phase power lines L1 and L2 to the outside terminals of the receptacle as shown in the illustration. Connect the center terminal to a good ground (cold water pipe or ground

rod). This grounds the Welder cabinet and prevents electric shock.

CAUTION: If the Welder is connected to one phase of a three phase line, do not connect the third phase wire to the ground terminal on the receptacle as this would result in a "live" cabinet. Recommended power line sizes are listed in the chart below.

POWER LINE SIZE CHART	
Line Voltage	Wire Size
208-230 V	6 AWG
440-460 V	10 AWG



CARE OF WELDER

Dust and dirt should not be allowed to accumulate on the transformer winding as it will cause excessive heating. Use an air hose to blow accumulation from windings.

Plugs and taps are normally kept clean by the wiping action created when they are coupled together in Welder operation. However, if not used for extended periods, the plugs and taps could corrode and become dirty. In such an event, wipe surfaces with extra fine sandpaper or steel wool.

Welder cabinet surfaces may be cleaned with auto wax.

Every 6 months the cabinet should be removed and the fan motor bearings oiled with a fine grade of motor oil.

CABINET HEATING

While the Welder is in use and especially under heavy load, the strong magnetic field within the cabinet will cause it to heat up. This is a natural effect and does not necessarily mean trouble.

OPERATION

CONNECTING THE WELDER

1. Turn Welder power switch OFF, then plug power cord into the 3-wire receptacle.
2. Turn power switch ON. (Fan should be operating.)
3. Connect the electrode and work cable plugs to desired taps on the Welder panel.
4. Attach work clamp to a clean area on the work and grip the uncoated end of the welding rod in the electrode holder.

GETTING READY TO WELD

Be familiar with the basic principles of arc welding.

Use the right electrode and current

1. For general purpose welding, use AWS E-6011 Mild Steel, AC-DC welding rod.*
2. The Electrode Size chart below is a guide showing which electrode sizes to use for various plate thicknesses.
3. The recommended currents for various electrode sizes are listed on the Welder nameplate.

Be Safe

1. Wear welding helmet to protect eyes and face from arc flash.
2. Wear gloves and apron to prevent burns due to welding spatter.
3. Provide adequate ventilation.
4. Be sure there is no combustible material in the work area.

*Other types of electrodes are described in the Welding Electrode Chart on page 6.


WELDING

After Connecting Welder and Getting Ready to Weld, the following should be observed:

1. Do not let electrode holder or electrode stub accidentally touch the work or the work clamp.
2. Never change taps while drawing an arc.
3. Turn welder off after using.

ELECTRODE SIZE CHART			
Plate Thickness	Electrode Diameter (Inches)		
	Horizontal	Vertical	Overhead
20 Ga.	1/16-3/32	3/32	3/32
18 Ga.	3/32	3/32-1/8	3/32-1/8
1/16"	3/32-1/8	1/8	1/8
1/8"	1/8"	1/8	1/8
3/16"	1/8-5/32	5/32	1/8
1/4"	1/8-5/32	5/32	1/8
5/16"	5/32-3/16	3/16	5/32
3/8" & Up	3/16-1/4	3/16	5/32

PARTS LIST



ORDERING INSTRUCTIONS

To avoid delays and assure correct replacement parts, always include the following information with the parts order:

1. Model and serial number. 2. Part number and description. 3. Quantity of parts desired.

NOTE: Do not use item numbers when ordering replacement parts.

ITEM	DESCRIPTION	PART NO.	ITEM	DESCRIPTION	PART NO.
1	Foot Assembly (left)	617-42058	13	Cable Plug Insulator	649-71222
	Foot Assembly (right)	617-40553	14	Transformer Weld Assy.	618-58257
2	Base Assembly	617-40555	15	Fan Motor	617-46861
3	Cabinet Wrap Assy.	617-58319	16	Fan Blade	626-59883
4	Front Panel Assembly	619-68912	17	Power Cord Set	633-58332
5	Nameplate	619-68909	18	Electrode Cable	634-67112
6	Terminal Panel (7 taps)	613-40046	19	Electrode Holder	685-40705
7	Terminal Panel (3 taps)	613-40222	20	Work Cable	634-67116
8	Terminal Nut	699-40529	21	Work Clamp	651-58847
9	Terminal Post Nut	699-50763	22	Helmet	50-132
10	Terminal Post Lockwasher	699-50976	23	Switch	627-47671
11	Terminal Post	611-50765	24	Insulator Pin	613-71223
12	Cable Plug	611-71219			

Manufacturer reserves the right to make changes in design, construction or materials as necessary.

WELDING ELECTRODE CHART

MILD STEEL ELECTRODES				HARD SURFACING ELECTRODES			
Marquette	ASTM-AWS Specification No.	Description	Welding Position & Current	BILD-UP-ROD No. 175	None	Brinell 300-435 as welded contact type electrode.	F, V, H AC or DC
POSITIVE-ROD No. 105	E-6010	All-Position, General Purpose electrode for fast, D.C. welding.	F, V, OH, H DCR	MANG-ROD No. 250	None	Brinell 190-250 As Welded. Work Hardens to 500-600.	F AC or DC
RED-ROD No. 130	E-6011	Special All-Purpose electrode for all repair and maintenance welding. Best results even on dirty rusty metal . . . poor fit ups.	F, V, OH, H AC or DC	*MANG-NICOL-ROD No. 255	None	Brinell 250-285 As Welded. Work Hardens to over 500.	F AC or DC
CODE-ROD No. 120	E-6012	HANDLES EASILY . . . on light sheet metal or heavy steel structures. Features Shallow Penetration with Good Fusion, and readily bridges the gaps on poor fit-up jobs.	F, V, OH, H DCS or AC	*HARD-ROD No. 285	None	Brinell 185-320 As Welded. Work Hardens to 485-500.	F AC or DC
PRODUCTION ROD No. 140	E-6013	All Purpose, All Position for fast, high quality production. GOOD APPEARING WELDS . . . work, has that "professional look", with closely rippled deposit.	F, V, OH, H AC or DC	HARD-ROD No. 450	None	Brinell 450-500 As Welded. Work Hardens to 550. For impact and abrasion.	F, V, H AC or DC
HY-PRO ROD No. 146	E-6014	All-position high speed production electrode with good penetration and easy slag removal.	F, V, OH, H AC or DC	*HARD-ROD No. 455	None	Brinell 500 as Welded. Work Hardens to 575.	F, V, H AC or DC
*MARQ-ROD No. 24	E-6024	High speed powdered metal coated contact type electrode for production welding. Selfstarting, permits "drag" technique for fast flawless welds of excellent appearance.	F, H Fillets AC or DC	HARD-ROD No. 550	None	Brinell 550-600 as welded. Work Hardens to 625. Excellent for high abrasion.	F, V, H AC or DC
PRESTO-ARC No. 15	None	A self starting, with easy re-starting powdered iron electrode. Smooth beads with ideal slag control.	F, H Fillets AC or DC	*HARD-ROD No. 555	None	Brinell 550 as Welded. Contact type electrode.	F, V, H AC or DC
*PREST-ARC No. 16	None	Stainless type electrode, 19-9 used for chrome plated, stainless, high carbon or galvanized steels. Also designed for Spot Gun.	F AC or DC	HARD-ROD No. 650	None	Rockwell C60-63 As Welded. Increase by liquid quenching.	F, V, H AC or DC
LOW ALLOY STEEL ELECTRODES				FOR WELDING CAST IRON			
*MARQ-ROD No. 7018	Iron Powder E-7018	Powdered iron coated, General Purpose, LOW HYDROGEN electrode for welding High Sulphur Steels, Hardenable Low Alloy, High Tensile Steels, Medium and High Carbon Steels, Cold Rolled Steels and Free Machining Steels.	F, V, OH, H AC or DC	BLU-ROD No. 40	STEEL CORE WIRE	All-Position, low cost, easy-to-use Cast Iron electrode for non machineable welding of cast iron.	F, V, OH, H AC or DCR
HY-TEST ROD No. 85	E-8011	All-Position Shielded-Arc electrode for welding alloy steels. High Tensile Strength 80,000 to 90,000 psi with extraordinary toughness.	F, V, OH, H AC or DC	NICOL-ROD No. 44	MONEL CORE WIRE	All-Position Machineable Cast or Malleable iron electrode that may also be used for welding Cast Iron or Steel . . .	F, V, OH, H AC or DC
HY-TEST ROD No. 110	E-10013	All-Position electrode for Welding High Tensile Steels. BUILD UP for HARD SURFACING . . . makes extremely strong base for hard-surfacing weld metal.	F, V, OH, H AC or DC	*NICOL-ROD No. 99	NICKEL CORE WIRE	Contact-type electrode for machineable welds in case and malleable irons. New Powdered metal coating increases arc stability. Requires less pre-weld and post-weld cleaning.	F, V, OH, H AC or DC
				BRONZ-ROD No. 61	BRONZE CORE WIRE	"Arc Brazing" electrode for Brazing Cast Iron, Malleable Iron, Steel, Copper, Silicon Bronze, etc. FOR DIFFICULT JOBS . . . oil-soaked, dirty, rusty or burned cast.	F, V, OH, H AC or DCR
				ALUMINUM-BRONZE No. 62	None	Use when high strength, tough ductile, corrosion resistance is needed. Welds alum. bronze, silicon bronze, malleable iron, gray cast.	F, V, H AC or DC
STAINLESS STEEL ARC WELDING ELECTRODES				FOR ALUMINUM WELDING			
STAIN-ROD No. 308	E-308-16	A.C. or D.C. All position use on 18-8 Stainless and on 11-14% Manganese Steels.	F, V, OH, H AC or DC	ALUMINUM-ROD No. 71	None	Ideal for all aluminum repairs, and fabrications. Core wire 95% alum. and 5% silicon. Produces smooth weld bead on flat, fillet or vertical jobs.	F, V, H DC (Rev. Pol.)
				FOR CUTTING			
				ARCUT-ROD No. 111	None	Cutting Electrode for Cutting, Gouging, Leveling, Scarfing and Piercing. Cuts through all metals.	F, V AC or DCS

* Metal powder coating, drag or contact type.