





COMMANDER 300 MACHINE SCHEMATIC G4357 REV: A



OCV TABLE
(ocv's measured at 1900 rpm)

MODE	MIN POT	MAX POT
CV	30.0vdc	62.0vdc
60		83.0vdc
90		83.0vdc
150		83.0vdc
230		83.0vdc
300		83.0vdc
CC	83.0vdc	83.0vdc

TABLE 1
(MEASURE FROM CONTROL BD J2-6 TO J2-2)

CONTROL DIAL POSITION	MODE SWITCH POSITION	DC VOLTAGE
MIN	CV	1.233-1.299
MIN	60A	1.868-1.984
MIN	90A	1.524-1.618
MIN	150A	1.162-1.234
MIN	230A	.844-.896
MIN	300A	.533-.587
MIN	CC	.319-.339
MAX	CV	4.799-5.095
MAX	60A	3.669-3.895
MAX	90A	2.998-3.184
MAX	150A	2.285-2.427
MAX	230A	1.660-1.762
MAX	300A	1.085-1.153
MAX	CC	3.870-4.110

* NOTE: Measured with respect to control board J2-2

** NOTE: To check shunt accuracy: Measure voltage from J3-6 to J3-15 use following formula to calculate weld current @ ampere results to accurate external meter.

(400)(volts) = actual weld amps

.050

COMMANDER 300 - CODES 10469, 10470, 10642, 10643

PRE-COMMON CONTROL WELD CONTROL SCHEMATIC

LEAD COLOR CODE:

- B-BLACK
- G-GREEN
- O-ORANGE
- R-RED
- U-BLUE
- W-WHITE
- Y-YELLOW

COMPONENT VALUE UNITS:

- CAPACITOR: MFD/VOLTS
- RESISTOR: OHMS/WATTS


CONNECTOR PIN NUMBERS:

EX. 12 PIN CONNECTOR

LABELS:

- COMMON
- FRAME GROUND
- EARTH GROUND


VIEW OF CONNECTOR ON PCB BOARD



CHOPPER PC BOARD

CHOPPER PCB FUNCTIONS:


- Receives 20 KHz PWM (pulse-width-modulated) signal from control PC board to control weld current via IGBT transistor modules.
- Receives board power from control transformer.



DISPLAY PC BOARD

DISPLAY BOARD FUNCTIONS:


- Receives scaled arc voltage and arc current signals from control board and uses them to display actual weld amps and volts.
- Receives control pot rail and wiper voltages from control board and uses them to display preset amps or volts.
- LED driver section and processor powered from 12v battery.
- Voltages from control board are optically isolated.



CONTROL PC BOARD

CONTROL PCB FUNCTIONS:


- Compares control pot setting vs. voltage and current feedback and regulates weld output via 20 KHz PWM (pulse-width-modulated) signals to chopper boards.
- Uses mode switch to change machine weld characteristics (CC-stick, CV-wire, pipe welding). Each tap changes control pot voltage rails and amplifier gains that control output load curves or slopes.
- Sends preset output volts and amps to display PC board.
- Sends actual output volts and amps to display PC board.
- Limits machine output current to 550 amps during first few milliseconds of arc start, and 400 amps thereafter.
- Provides start enhancement for CC and CV modes.
- Provides arc force control in CC mode by sensing short circuit condition and then boosting current according to arc force/pinch pot setting.
- Provides bead control in CV by controlling average current according to arc force/pinch pot setting.
- Sends signal to engine protection PC board when sensing more than 20 amps of weld current.
- Receives signal from engine protection board to turn weld output on at "weld terminal" switch or remote 2-4 switch closure.
- Receives board power from control transformer.



ENGINE PROTECTION PC BOARD

ENGINE PROTECTION PCB FUNCTIONS:

- Controls engine start up and shutdown via shutdown solenoid.
- Controls engine speed via idle solenoid. (Idle solenoid driven in same manner as shutdown solenoid.)
- Protects the engine against low oil pressure, over-temperature, and no alternator output. Indicates engine fault via panel lights.
- Blocks engine sensors during first 30 seconds of power up to allow engine to reach operating speed and stability.
- Flashes engine alternator and rotor field during first 30 seconds of power up.
- Senses weld current and auxiliary current flow and then picks machine up to hi idle in "auto idle" mode.
- Provides 12 second delay from hi to low idle when no weld or auxiliary current is sensed.
- Shuts down engine in 30 minutes if low fuel condition is sensed. Indicates low fuel via panel light.
- Provides 5 second lamp test at machine power up (all panel lights on).
- Senses "welding terminal" switch and remote 2-4 switch closure. Sends signal to control board to turn output on or off.
- Receives board power from 12v battery.



QUICK TROUBLESHOOTING TIPS

SYMPTOM	CHECK
No weld output	- aux pwr ok?; flashing ok? - bad chopper pcb?; broken leads at chopper pcb plug? - bad 5 & 6 leads at J30/P30? - imbalance protection - disconnect leads 68 & 69
Won't make max output	- low field?; Bad field capacitor? - engine rpm's low?; bad fuel? - bad control pcb?
Erratic arc/ No control	- voltage feedback & current feedback ok? - bad control pot or mode switch? - bad remote switch?
Dead display	- broken leads at display board? - flashing ok?
No low idle	- no loads on weld studs or receptacles? - plunger sticking? long stickout? - voltages at idle sol. coil ok? - bad engine protection pcb?
No hi idle	- machine won't load? - bad idle switch? - bad engine protection pcb?
Won't start	- dead battery? - voltages at shutdown sol. coil ok? - bad engine protection pcb?
Display pcb calibration	- set control panel as follows: C32 Weld Terminals sw to "Remotely Controlled" Local/Remote sw to "Local" Range Selector sw to "90A" Control Dial to "minimum"(ccw) High/Auto Idler sw to "high" Arc Force dial to "minimum"(ccw) - start the engine. While the display reads "CDR 500", switch the Selector Switch to the CV tap and back to the 90A tap a minimum of 5 times. Selector Switch must end up in the 90A position. - top display should read "001" for 5 sec, then "cal" for 5 sec - top display should read "30", bottom should read "..."

COMMANDER 300 - CODES 10469, 10470, 10642, 10643

PRE-COMMON CONTROL PC BOARD AND OPERATION DESCRIPTIONS

LEAD COLOR CODE:
 B-BLACK
 G-GREEN
 O-ORANGE
 R-RED
 U-BLUE
 W-WHITE
 Y-YELLOW

COMPONENT VALUE UNITS:
 CAPACITOR: MFD/VOLTS
 RESISTOR: OHMS/WATTS

CONNECTOR PIN NUMBERS:
 EX 12 PIN CONNECTOR

LABELS:
 COMMON
 FRAME GROUND
 EARTH GROUND

VIEW OF CONNECTOR ON PC BOARD