

COOL ARC 55 S MACHINE SCHEMATIC L16403-1 REV : A

ERROR CODES		
ERROR	EXPLANATION	INDICATION
92	FLOW SENSOR FAULT	THE FLOW SENSOR IS NOT DETECTING PROPER FLOW. CHECK TO MAKE SURE ALL HOSES ARE CONNECTED AND THAT THERE IS ENOUGH COOLANT IN THE SYSTEM. BE SURE THE SYSTEM IS PRIMED AS DESCRIBED IN THE OPERATION SECTION OF THE MANUAL. THERE COULD ALSO BE A BLOCKED LINE OR PUMP FAILURE.

