LINCOLN ELECTRIC EUROPE



Service Notice N°: ESN0079 Rev.00 Date: 12 October 21

Random shut down of front panel PCB

| Product | K Number | Code Number | Serial Numbers |
|---------------------|------------|-------------|----------------|
| PRESTOTIG 180 FORCE | W000382577 | - | |
| PRESTOTIG 220 FORCE | W000382578 | - | |
| CITOTIG 1800 FORCE | W000382579 | - | |
| CITOTIG 2200 FORCE | W000382580 | - | |
| INVERTEC 175TP | K14169-1 | 50394 | |



WARNING

Be sure that only qualified individuals perform all installation, operation, maintenance and repair procedures. Lincoln Electric is not responsible for damages caused by improper installation, improper care or abnormal operation.

Before opening or disassembling any parts of the product, the power must be turned OFF and the product must be disconnected from the input power source. Only Lincoln trained service technicians are authorized to perform these modifications.

Explanation of the Problem

Randomly front panel display shutdown completely even if the recommendations listed into the ESN0078 have been applied

Correction of the Problem

Problem can be solved by adding a capacitor on PCB control panel

