



AC-225 WELDER 230 VOLT/ 60 HERTZ WIRING DIAGRAM S15621 REV-B

CUSTOMER CONNECTION OF RECEPTACLE TO POWER SUPPLY

WARNING TURN OFF INPUT POWER USING THE DISCONNECT SWITCH AT FUSE BOX BEFORE CONNECTING RECEPTACLE OR WORKING ON MACHINE.



THE LINCOLN ELECTRIC COMPANY

World's Leader in Welding and Cutting Products
Sales and Service through Subsidiaries and Distributors Worldwide
Cleveland, Ohio 44117-1199 U.S.A.