



AC/DC 1000 WIRING DIAGRAM G4076-1 REV: A

LEFT SIDE OF MACHINE



- NOTES:
- N.A. CONNECT TO TRANSFORMER LEADS FROM POWER SOURCE
 - N.B. CONNECT TO OUTPUT RECTIFIER HEATSINK IN POWER SOURCE
 - N.C. CONNECT TO 206A IN POWER SOURCE (VOLTAGE FEEDBACK)
 - N.D. CONNECT TO OUTPUT STUD IN POWER SOURCE (CENTERTAP CONNECTION)
 - N.E. CONNECT TO POWER RESEPTACLE IN POWER SOURCE
 - N.F. CONNECT TO INTERFACE CABLE IN POWER SOURCE



CLEVELAND, OHIO, U.S.A.