POWER WAVE 455 MACHINE SCHEMATIC G3181-2 REV: D



NOTES :

N.A. PC BOARD COMPONENTS SHOWN FOR REFERENCE ONLY.
ALL COMPONENTS ARE NOT SHOWN.

N.B. L2 IS WOUND ON ONE COMMON CORE.

N.C. T1 PRIMARY CONNECTIONS SHOWN FOR REFERENCE ONLY.
SEE WIRING DIAGRAM FOR 460/575 SWITCHING.