



110-108


Replacement Parts List Model 110-108



Amp Draw - 46 MAX
30 ARC Volt LEND

Item	Part Number	Description
1.	410-215-010	Welder Base
2.	441-022-000	Foot
3.	541-004-000	Strain Relief
4.	238-113-000	Ground Cable Assembly
5.	541-019-000	Strain Relief
6.	711-130-010	Face Plate
7.	316-007-000	Fan Blade
8.	216-043-000	Fan Motor
9.	411-072-000	Fan Mounting Bracket
10.	216-042-000	Switch
11.	860-402-000	Shunt Assembly
12.	218-089-000	Power Cord
13.	860-427-000	Transformer Assembly
14.	312-028-000	Receptacle Assembly
15.	410-209-100	Cover (not shown)





110-108

