


VANTAGE 400 WIRING DIAGRAM G7140 REV: A



NOTE:
FERRITE ON
LEADS 75A & 76A
(3 TURNS)

FERRITE ON
TWISTED PAIR
4 TURNS

LEADS 234A & 236D ARE NOT USED ON THIS MACHINE.



CLEVELAND, OHIO, U.S.A.