


VANTAGE 500 WIRING DIAGRAM G10021-1 REV: B



NOTE:
FERRITE ON
LEADS 75A & 76A
(3 TURNS)

FERRITE ON
TWISTED PAIR
4 TURNS

B1 AND FLY LEAD USED ON G8610-1 ONLY;
NOT USED ON G5507-4.