


# VANTAGE 322 (KUBOTA) WIRING DIAGRAM G7137-2 REV:B



B1 AND FLY LEAD USED ON G8610-1 ONLY;  
NOT USED ON G7637-4.