




REPAIR PARTS LIST

Code No.	Part No.	Description	No. Req'd
1	30100100	Phillips Head Screw	4
2	61986288	Cabinet (Marquette)	1
	61986285	Cabinet (NAPA)	1
3	30100108	Screw	17
4	31100035	Lockwasher	2
5	69941015	Screw	2
6	95080933	Transformer w/Shunt Assembly	1
7	69941123	Hex Nut	2
8	69942176	Hex Head Screw	2
9	39900153	Shunt Slide	2
10	39900157	Shunt Support	2
11	39900133	Indicator	1
12	48000005	Strain Relief	1
13	69983523	Jam Nut	6
14	31100039	Receptacle Washer	3
15	69941206	Flat Washer	9
16	69946751	Lockwasher	3
17	95080898	Power Cord	1
18	43600027	Switch	1
19	21000373-225	Cabinet Wrap (Marquette)	1
	21000373-191	Cabinet Wrap (NAPA)	1

Code No.	Part No.	Description	No. Req'd
20	21500014	Crank	1
21	30000055	Screw	1
22	36400013	Shoulder Bushing	1
23	66548976	Snap Bushing	1
24	39900132	Fan Blade	1
25	30300036	Hex Nut	2
26	21000365	Fan Bracket	1
27	69977213	Hex Nut	2
28	44200010	Fan Motor	1
29	69941387	Washer	2
30	69941045	Screw	2
31	46600066	Receptacle	3
32	14900032	Receptacle Insulator	3
33	95080911	Weld Cable Assembly	1
34	68540705	Electrode Holder	1
35	95080910	Ground Cable Assembly	1
36	99900007	Ground Clamp Kit	1
37	95080913	Shunt Assembly	1


NUMERICAL PART LISTING

Part No.	Code No.	Part No.	Code No.	Part No.	Code No.
14900032	32	39900133	11	69941123	7
21000365	26	39900153	9	69941206	15
21000373-191	19	39900157	10	69941387	29
21000373-225	19	43600027	18	69942176	8
21500014	20	44200010	28	69946751	16
30000055	21	46600066	31	69977213	27
30100100	1	48000005	12	69983523	13
30100108	3	61986285	2	95080898	17
30300036	25	61986288	2	95080910	35
31100035	4	66548976	23	95080911	33
31100039	14	68540705	34	95080913	37
36400013	22	69941015	5	95080933	6
39900132	24	69941045	30	99900007	36

ORDER BY PART NUMBER, NOT BY CODE NUMBER

WIRING DIAGRAM

Arc Welder Model No. 10-134/83-314



CIRCUIT DIAGRAM