


DC-1000 WIRING DIAGRAM G2147-1 REV: B



LED 1 = 42V INPUT
 LED 2 = VOLTAGE FEEDBACK
 LED 3 = 24 VDC SUPPLY
 LED 4 = FAULT
 LED 5 = SCR CONTROL SIGNAL

LED 1 - 2 = SCRS 1 - 2 FIRING SIGNAL
 LED 3 - 4 = SCRS 3 - 4 FIRING SIGNAL
 LED 5 - 6 = SCRS 5 - 6 FIRING SIGNAL
 LED 7 - 8 - 9 = INPUT PHASE ANGLE VOLTS