PROPER SELECTION OF A SWITCHOVER MANIFOLD

APPLICATIONS

GAS SERVICE

1.

2.

3.

Non-Corosive Blanketing 200 Maximum inlet pressure 3000 Flammable psig Oxygen Purging Duplex or Simplex design Cutting & welding Master shut off valve High Flow Integrated CGA check valves to eliminate atomspheric contamination 99% purity Non-Corosive Blanketing 220 Maximum inlet pressure 3000 Flammable Purging psig Cutting & welding Automatic switchover based off Oxygen High Flow pressure 99% purity Indicating lights to notified user when changeover occurred Pressure gauges to provide visual pressure status Enclosed box design to protect inter parts and better appreance High pressure verious high pressure CO2 / N2O available with internal heater

MODEL

FEATURES