

# LADI Analog-Digital Interface

---

|                                  |   |
|----------------------------------|---|
| Spare Parts .....                | 1 |
| Figure A: Machine Assembly ..... | 1 |
| Electrical Schematic .....       | 2 |
| CODE: 50330 .....                | 2 |



Lincoln Electric Bester Sp. z o.o.  
ul. Jana III Sobieskiego 19A, 58-260 Bielawa, Poland  
[www.lincolnelectric.eu](http://www.lincolnelectric.eu)

# Spare Parts

SP50322 REV01  
01/2024

| ASSEMBLY<br>PAGE NAME |          |             | Central<br>Assembly |  |  |  |  |  |
|-----------------------|----------|-------------|---------------------|--|--|--|--|--|
| CODE NO.:             | K NO.:   | FIGURE NO.: | A                   |  |  |  |  |  |
| 50330                 | K14152-1 | LADI        | 1                   |  |  |  |  |  |

\*items highlighted in bold are recommended spare parts




Figure A

Figure A: Machine Assembly

| Item | Description                               | Part Number          | QTY | 1 | 2 | 3 | 4 | 5 | 6 | 7 |
|------|-------------------------------------------|----------------------|-----|---|---|---|---|---|---|---|
| 1    | LED LAMP H1                               | 0917-421-009R        | 1   | X |   |   |   |   |   |   |
| 2    | USB SOCKET X5                             | 1158-641-061R        | 1   | X |   |   |   |   |   |   |
| 3    | SOCKET X11 COVER                          | 1158-641-159R        | 1   | X |   |   |   |   |   |   |
| 4    | SOCKET X4                                 | C-2986-001-3R        | 1   | X |   |   |   |   |   |   |
| 5    | COVER WITH DECAL                          | R-1019-467-1R        | 1   | X |   |   |   |   |   |   |
| 6    | COVER WITH DECALS                         | R-3019-388-1R        | 1   | X |   |   |   |   |   |   |
| 7    | WELD CABLE X3                             | R-5041-414-1R        | 1   | X |   |   |   |   |   |   |
| 8    | CONTROL CABLE X10                         | R-5041-415-1R        | 1   | X |   |   |   |   |   |   |
| 9    | HARNESS                                   | R-5041-416-1R        | 1   | X |   |   |   |   |   |   |
| 10   | <b>P.C.BOARD (ANALOG-DIGITAL CONTROL)</b> | <b>R-6042-073-1R</b> | 1   | X |   |   |   |   |   |   |
| 11   | CURRENT SENSOR                            | W4900004R            | 1   | X |   |   |   |   |   |   |
| 12   | P.C.BOARD (40VDC SUPPLY)                  | R-8040-348-1R        | 1   | X |   |   |   |   |   |   |

Electrical Schematic

CODE: 50330

