


VANTAGE 322 WIRING DIAGRAM G10317 REV: B



B1 AND FLY LEAD USED ON G8610-1 ONLY; NOT USED ON G5507-4.

