

Service Information: 16-September-2024

TIG torches WTT2

Issue when using Remote controls on 275-300-400 Invertec[®] TP

If TIG torch models WTT2 are used with new Invertec[®] 275-300-400TP equipment in combination with hand (K14147-1/K10095-1-15M) or foot remote controls (K870) to have them working it is necessary to remove the jumper that is present between pin 4 & 5 inside of the CB5 connector on TIG torch trigger cable.

