

INVERTER RACKS

COMPACT, RUGGED AND COMPLETE



Shown:
Flextec® 350X Construction 4-Pack Rack (K3402-1)
(Expandable to 8-Pack Rack with a Flextec 350X
4-Pack to 8-Pack Rack Conversion Kit (K3410-1)).

KEY FEATURES

Lincoln Electric's inverter racks are ideal for field construction where multiple arcs are needed. Benefit from more portability, smaller footprint and a single primary input connection for multiple welders.

Processes »

Flextec 350X, 500X and 650X: Stick, TIG, MIG, Flux-Cored, Gouging

Invertec V276: Stick, TIG, Gouging

Output »



Input »



Product Numbers »

See Back

⁽¹⁾Invertec V275-S only ⁽²⁾Flextec racks only

FEATURES

- **One easy connection** – Allows power sources to be connected with one primary power drop
- **The power sources are factory installed** in the rack and wired to the main power distribution panel
- **Entire system meets National Electrical Code (NEC)** – Compare the best in class rated output and wide amperage range
- **Individual fuses** – Provide overcurrent protection for each power source
- **Two overhead lifting eyes, fork lift slots⁽¹⁾, and heavy duty optional casters** – Provide ease of portability
- **Optional Caster Kit** – Available for Inverter Racks. Order K2665-1
- **Accommodates standard length machine input cables** – Ensures the power sources can be placed in any position on the rack
- **Units are IP23 or IP23S Rated** – Depending on model
- **Fold Down fuse panel** – Makes it more convenient to access wiring and change fuses (Flextec models only)
- **Square tube frame construction** – Supports more weight and stands up to rugged job site use

RACKS

Flextec Racks



K3402-1 Flextec 350X Construction 4-Pack Rack

K3403-1 Flextec 350X Standard 4-Pack Rack

K4726-1 Flextec 350X PowerConnect® 4-Pack Rack



K3410-1 Expandable to 8-Pack Rack
[shown with Flextec 350X 4-Pack to 8-Pack Rack Conversion Kit [K3410-1]]



K4466-1 Flextec 500X 4-Pack Rack

K3510-1 Flextec 650X 4-Pack Rack



K4277-1 Flextec 350X Construction 6-Pack Rack

K4281-1 Flextec 350X Standard 6-Pack Rack

K4727-1 Flextec 350X PowerConnect® 6-Pack Rack

K4465-1 Flextec 500X 6-Pack Rack



K4869-1 Invertec V276 4-Pack Rack



K4869-2 Invertec V276 8-Pack Rack

⁽¹⁾ Fork access configuration varies by rack model

RECOMMENDED ACCESSORIES

GENERAL OPTIONS

Empty Racks with Distribution Boxes



Flextec 350X Empty 4-Pack Rack

Complete rack assembly without welders. Includes 35A fuses.
Order K3400-2

Empty Flextec 350X 6-Pack Rack

Includes 35A fuses
Order K4769-1

Empty Flextec 500X 4-Pack Rack

Includes 50A fuses
Order K4770-1

Empty Flextec 500X 6-Pack Rack

Includes 50A fuses
Order K4771-1

Empty Flextec 650X 4-Pack Rack

Includes 60A fuses
Order K4772-1

Empty Invertec V276 4-Pack Rack

Include 35A fuses
Order K4928-1

Empty Invertec V276 8-Pack Rack

Include 35A fuses
Order K4928-2

Replacement 35A Fuse for Flextec 350X
3 req'd per machine
Order 9SS28499-13

Replacement 50A Fuse for Flextec 500X
3 req'd per machine
Order 9SS28499-12

Replacement 60A Fuse for Flextec 650X
3 req'd per machine
Order 9SS29404

Replacement 35A Fuse for Invertec V350 PRO
3 req'd per machine
Order 9SS25439-15

Flextec 350X 4-Pack to 8-Pack Rack Conversion Kit
Expand the 4-Pack Rack (K3400-1) with or without welders to an 8-Pack Rack.
Order K3410-1



Flextec 350X Locking Foot Kit
Required when adding Flextec 350X welders to an empty rack.
Order K4424-1



Rack Caster Kit
Add heavy duty casters to any rack.
Order K2665-1



Tweco®-Style Plug
Male, 1/0 Thru 2/0
Order K3416-70



Tweco-Style Receptacle
Female, 1/0 Thru 2/0
Order K3417-70



Tweco-Style Plug
Male, 3/0 Thru 4/0
Order K3416-90



Tweco-Style Receptacle
Female, 3/0 Thru 4/0
Order K3417-90

Lug to Tweco-Style Receptacle
Order K2487-1

PRODUCT SPECIFICATIONS

Product Name	Product Number	Output Connection	Rack Input Power ⁽¹⁾	Rated Output Current/ Voltage/Duty Cycle ⁽²⁾	Rack Input Current @ Rated Output	Output Range (amps)	H x W x D in (mm)	Net Wt. lb (kg)
Flextec 350X Racks								
4-Pack Rack Construction Model (Compact)	K3402-2	Tweco	380/460/575/3/50/60	350A/34V/60% 300A/32V/100%	74/68/68 (4-Pack) 125/113/113 (8-Pack)	5-425A	59.72 x 37.25 x 32.88 (1516 x 946 x 835)	620 (281)
4-Pack Rack Standard Model (Compact)	K3403-2							
4-Pack Rack PowerConnect model (Compact)	K4726-1		200/230/380/460/575/3/50/60		4-Pack: 131/118/68/57/46 8-Pack: 219/197/114/95/77		59.72 x 37.25 x 32.88 (1516 x 952 x 835)	644 (292)
6-Pack Rack Construction Model	K4277-1		380/460/575/3/50/60		100/90/90		71.22 x 48 x 35.5 (1809 x 1219 x 902)	830 (377)
6-Pack Rack Standard Model	K4281-1							
6-Pack Rack PowerConnect Model	K4727-1							
Flextec 500X Racks								
4-Pack Rack	K4466-1	Lug	380/460/575/3/50/60	500A/40V/60% 450A/38V/100%	103/75/61A	5-500A	71.22 x 36 x 35.5 (1809 x 914 x 902)	800 (363)
6-Pack Rack	K4465-1				138/100/81A			1100 (498)
Flextec 650X Racks								
4-Pack Rack	K3510-1	Lug	380/460/575/3/50/60	650A/44V/100% 750A/44V/60%	202/167/103A	10-815	71.22 x 36 x 35.5 (1809 x 914 x 902)	960 (435)
Invertec V276 Racks								
Invertec V276 4-Pack Rack	K4869-1	Tweco	*208/230/460/575/3/60	*275A/31V/35% 250A/30V/60% 200A/28V/100%	96/89/46/39A	20-275	59-72 x 37.5 x 32.88 (1516 x 952 x 835)	644 (292)
Invertec V276 8-Pack Rack	K4869-2				161/149/77/65A		58 x 42 x 29 (1474 x 1067 x 737)	750 (341)

⁽¹⁾ Fused for 380/460/575/3/50/60 VAC operation. For 230 or 208 VAC operation, primary fuses must be changed.

⁽²⁾ Based on a 10 minute period. Output is for each individual machine.

For best welding results with Lincoln Electric® equipment, always use Lincoln Electric consumables. Visit www.lincolnelectric.com for more details.

CUSTOMER ASSISTANCE POLICY

The business of The Lincoln Electric Company® is manufacturing and selling high quality welding equipment, consumables, and cutting equipment. Our challenge is to meet the needs of our customers and to exceed their expectations. On occasion, purchasers may ask Lincoln Electric for information or advice about their use of our products. Our employees respond to inquiries to the best of their ability based on information provided to them by the customers and the knowledge they may have concerning the application. Our employees, however, are not in a position to verify the information provided or to evaluate the engineering requirements for the particular weldment. Accordingly, Lincoln Electric does not warrant or guarantee or assume any liability with respect to such information or advice. Moreover, the provision of such information or advice does not create, expand, or alter any warranty on our products. Any express or implied warranty that might arise from the information or advice, including any implied warranty of merchantability or any warranty of fitness for any customers' particular purpose is specifically disclaimed.

Lincoln Electric is a responsive manufacturer, but the selection and use of specific products sold by Lincoln Electric is solely within the control of, and remains the sole responsibility of the customer. Many variables beyond the control of Lincoln Electric affect the results obtained in applying these types of fabrication methods and service requirements.

Subject to Change – This information is accurate to the best of our knowledge at the time of printing. Please refer to www.lincolnelectric.com for any updated information.

The Lincoln Electric Company
22801 St. Clair Avenue · Cleveland, OH · 44117-1199 · U.S.A.

All trademarks and registered trademarks are the property of their respective owners

www.lincolnelectric.com