


RED-D-ARC FX360 WIRING DIAGRAM G7148-3 REV: A



LEFT SIDE OF MACHINE

REAR OF MACHINE

FRONT OF MACHINE


RIGHT SIDE OF MACHINE

GENERAL INFORMATION
ELECTRICAL SYMBOLS PER E1537.

LEAD COLOR CODING
B - BLACK
R - RED
N - BROWN
V - VIOLET
G - GREEN
U - BLUE

CAVITY NUMBERING SEQUENCE
(VIEWED FROM COMPONENT SIDE OF P.C. BOARD)

PIN NEAREST THE FLAT EDGE OF LED LENS (ANODE) ALIGNS WITH WHITE LEAD OF LED SOCKET.



NOTES:
N.A. PIN NEAREST THE FLAT EDGE OF LED LENS ALIGNS WITH WHITE LEAD OF LED SOCKET.
N.B. PLACE "A" LEAD ON APPROPRIATE CONNECTION FOR INPUT VOLTAGE. CONNECTION SHOWN IS FOR 575V OPERATION.

N.D. LEDs ARE ONLY ACTIVE IF VRD IS TURNED ON.

