



AC-1200 50/60HZ MODELS WIRING DIAGRAM M18868 REV: C

NOTES:
 N.A. CENTER TERMINAL OF FUSE HOLDER
 N.B. 20 AMP SLOW BLOW FUSE (NOT PRESENT ON EARLY MODELS).



CLEVELAND, OHIO U.S.A.