





Century bench chargers and battery testers are not repaired at service shops. If one fails in warranty (within one year), they are replaced after being received at the factory (1-866-236-0044, #22).

Models covered by this policy: 87001, 87002, 87062C, 87101, 87102, 87105C, 87106C, 87120, 87121, 87122, 87150, 87151C, 88100

| Wiring | Diagrams | | | | |
|------------|------------|--------|-------|-------|------------|
| 87001 | 87101 (NA) | 87105C | 87120 | 87122 | 87151C |
| 87002 (NA) | 87102 | 87106C | 87121 | 87150 | 88100 (NA) |
| 87062C | | | | | |







